



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,982,764
Version:	1
Created:	17 Jan 2020

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00505903
Year:	2011	Odometer:	97,701 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	4.0	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>4.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	4.0	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>5.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	5.0	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	6.0	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	90	R/H Doors	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	68	Heater Fan	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	•	44	Front Brakes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	74	Seats	Good	94	Front Bumper	Good
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	75	Carpets	Good	76	Panels	Good	95	Rear Bumper	Good
16	Dashboard Warning Lights	✓	46	Handbrake	✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>78</td> <td>Fuel Cap</td> <th>✓</th> <td>96</td> <td>Roof</td> <td>Good</td>	77	Dashboard	Good	78	Fuel Cap	✓	96	Roof	Good
17	Speedo	✓	Keys and Locking		47	Central Locking	✓ <td>79</td> <td>Bonnet</td> <td>Good</td> <td>97</td> <td>Mud Flaps</td> <th>✓</th>	79	Bonnet	Good	97	Mud Flaps	✓	
18	Odometer	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>80</td> <td>WOF</td> <th>✓</th>	49	Number of Keys	1	80	WOF	✓			
19	Rev Counter	•	Engine		50	Oil Level	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good				
20	Fuel Gauge	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	52	Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good			
21	Wipers Front/Rear	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	54	Starter Motor	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good			
22	Window Opener FL	✓							84	Rear Wiper Blade	Good			
23	Window Opener FR	✓							85	R/H Mirror	Good			
24	Window Opener RL	✓							86	L/H Mirror	Good			
25	Window Opener RR	✓							87	L/F Guard	Good			
26	Rear View Mirrors	✓							88	R/F Guard	Good			
27	Radio (Basic Test Only)	✓							89	L/H Doors	Good			
28	CD (Basic Test Only)	✓							90	R/H Doors	Good			
29	Boot Open Switch	✓							91	L/H Sill	Good			

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	16 Jan 2020
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--