

Report ID: 19,984,165 Version: 1 24 Feb 2020 Created:

Make:	Volkswagen	Model:	Amarok	Body Style:	Utility	]		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JCM676 <b>Reg Expiry:</b> 01 Jul 2020		Engine					
WoF Expiry:	07 Feb 2021	Odometer:	141,214 Kms	Good No:	19984165	Oil level		<b>~</b>		
VIN:	WV1ZZZ2HZFA01186	Next Service:	151185	Service Histor	<b>y:</b> No	Smoke & fumes		~		
						Performance		~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	on	~		
	SC		SC SC		S SC	Performance		~		
Key:		-0				Radiator / Hoses	s (visual)	~		
S = scratch D = dent						Transmission		1		
D = dent R = rust	s sc			715	HIVSW	Operation		~		
PT = paint defe	ect NP				70111	Noise		~		
C = crack					SC	Clutch				~
P = pin dent	HIP				74JUL	CV joints		~		
* = decals SC 99 SD						Wheel bearings	;	~		
SC = stone chips W = significant scuffs						Brakes				
W = significant scutts S D PT						Performance		~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake		~		
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)				es)
						Left front 4			mm	
						Right front		4 m		mm
						Left rear		7		mm
Conditions During Body Inspection: Dry						Right rear	7		mm	
						Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension per	formance	~		
						Steering perform	mance	~		
						Shock absorber	s	~		
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	wear and t	ear,				Head lights		~		
Carpote	Good					Tail lights		~		
Carpets						Indicators		~		
Panels	glasses ho	lder in the roof ir	nterior broken ,			Dashboard war	ning lights	<b>~</b>		
Dachhar	Good					Wipers (front &	rear)	~		
Dashboa	iiu					Window winder	r FL	<b>~</b>		
						Window winder	r FR	~		
General C	<u>Comments</u>					Window winder	r RL	<b>~</b>		
						Window winder	r RR	•		
						Rear view mirro	rs	•		
						Radio (basic test	t only)	•		
						CD (basic test or		<b>~</b>		
							Number of keys 1			
Road Conditions During Test Drive: Dry						Central locking		•		
Engine Timing Mechanism.						Remote locking		•		
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic t	test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing came	era			~
Inspected by: Donovan Matara Date: 24 Feb 2020										

I have read and understood this condition guide.

Name: .....

Signature: .....