

Report ID: 19,984,623 Version: 1 16 Jan 2020 Created:

| Make: | Toyota | Model: | Vitz | Body Style: | Hatchback | | Pass | Fail | N/A |
|---|--------------------------|----------------------|------------------------|---------------------------------------|----------------------|-----------------------------|---------|---------|-----|
| Year: | 2001 | Registration: | FRR175 | Reg Expiry: | 08 Jul 2020 | Engine | | | |
| WoF Expiry: | 10 Jul 2020 | Odometer: | 117,166 Kms | Good No: | 19984623 | Oil level | ~ | | |
| VIN: | 7AT0H63EX10316750 | Next Service: | 126,000kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | SD D | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | w dla | | | 715 | S D PT | Operation | ~ | | |
| PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74114 | CV joints | ~ | | |
| * = decals | DSC 916 | | | The | ALC P | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S S S S D C S D S D | | | | | | Performance | ~ | | |
| Dealerteen | <u></u> | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed trea | d depth | of tyre | es) |
| Rear door handles loose x2/Left headlight faded/Left wing mirror damage/Remote key fail | | | | | | | | | mm |
| | | | | | | Right front | | 5 5 | mm |
| | | | | | | Left rear | | 5 | mm |
| Conditions During Pody Inspection: Dry | | | | | | Right rear | | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Engine oil le | eak - oil sump | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Poor | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | I | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | 1 | L |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | 2 V | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | - | ~ | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | | - | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | - | | | | | |
| Inspected by: Ca Thach Date: 16 Jan 2020 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: