

## **Basic Vehicle Condition Guide**

Report ID: 19,989,712

Version: 1

Created: 30 Jan 2020


Make:HondaModel:StreamBody Style:SUVYear:2008Registration:Reg Expiry:

 WoF Expiry:
 17 Jan 2021
 Odometer:
 47,889 Kms
 Good No:
 19989712

 VIN:
 7AT08GADX20060785
 Next Service:
 57000 km
 Service History:
 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Dry

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 30 Jan 2020

Name: .....

	Pass	Fail	N/A
Engine	1 433	Tan	IN/A
Oil level	<b>4</b>		
Smoke & fumes	\( \times \)		
Performance	•		
Noise	./		
Cooling System			
Cooling System  Coolant condition			
Performance	V		
Radiator / Hoses (visual)			
Transmission	•		
Operation			
Noise			
Clutch	-		
			· ·
CV joints	•		
Wheel bearings	•		
Brakes Performance			1
	•		
Hand Brake	l alasatis	- 6 4	
Tyres (lowest observed tread Left front		-	
		3	mm
Right front		3	mm
Left rear		3	mm
Right rear	8	3	mm
Spare		Yes	
Suspension			
Suspension performance Steering performance	•		
	<b>V</b>		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			
Head lights	<i>V</i>		
Tail lights	<i>V</i>		
Indicators  Dashboard warning lights			
Dashboard warning lights	V V V V V V V V V V V V V V V V V V V		
Windowwinder Fl	•		
Window winder FL	•		
Window winder FR	•		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors			
Radio (basic test only)	-		
CD (basic test only)	_		•
Number of keys	2		
Central locking	•		
Remote locking	-		_
Sat. Nav. (basic test only)			-
Reversing camera	<b>'</b>		

Signature: .....