

Basic Vehicle Condition Guide

Report ID: 19,992,334


Version: 1

Created: 29 Jan 2020

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2014 Registration: HUC713 Reg Expiry: 15 Mar 2020 **Odometer:** WoF Expiry: 22 Nov 2020 170,292 Kms **Good No:** 19992334 VIN: MR0EZ12G804014587 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rubber trim coming off lower edge of canopy both sides. Trailer electrical coupling not secure. Has jack but no tools. Stonechips on windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Both front tires have inner edge wear.

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Drives well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 151,719

29 Jan 2020 Inspected by: Roger King Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>v</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | V | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | • | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | | 1 | mm |
| Right front | | 2 | mm |
| Left rear | | 2 | mm |
| Right rear | 1.8 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | \(\times \) | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | <i>'</i> | | |
| Window winder FL | - | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | · | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 3 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | <u>'</u> |

Signature: