

Report ID: 19,996,504 Version: 3 13 Mar 2021 Created:

Make:	Toyota	Model:	Prius	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2009	Registration:		Reg Expiry:		Engine	I		I	
WoF Expiry:		Odometer:	76,403 Kms	Good No:	19996504	Oil level	~			
VIN:	7AT0H637X20056540	Next Service:	81276 kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.										
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
		_				Performance	~			
Key:		-0		-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	•			
D = dent				TIN		Operation	~			
R = rust PT = paint defe				\prod		Noise	~			
C = crack				+		Clutch			~	
P = pin dent					세비	CV joints	~			
* = decals				-NL	ELIPS-	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note: son	ne defects & blemishes	may not be disc	blaved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	 >S)	
Left rear tyre wall cut					Tyres (lowest observed tread depth of tyres) Left front 7 mm					
						Right front			 mm	
						Left rear			mm	
			_			Right rear			mm	
Conditions During Body Inspection: Dry										
Under Carriage & Under Bonnet Inspection Comments					Spare Yes Suspension					
Front whee	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	V			
						Operation				
Interior Comments						Operation Electrical / Accessories				
Good										
Seats							v			
Carpets	Good					Tail lights Indicators	V 			
	Good						V 			
Panels						Dashboard warning lights	V			
Dashboa	rd Good					Wipers (front & rear)	v			
						Window winder FL	~			
General Comments					Window winder FR	~				
	<u>connents</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanism: Timing Chain						Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
				11115.		Reversing camera	~			
Inspecter	Inspected by: Mathew Varghese Date: 13 Mar 2021									
L	,									

I have read and understood this condition guide.

Name:

Signature: