



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,998,087
Version:	1
Created:	11 Feb 2020

Make:	Nissan	Body Style:	SUV
Model:	X-Trail	VIN:	7AT0DH6LX20038421
Year:	2009	Odometer:	92,315 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle					
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•			
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good		
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		3.5	mm	85	R/H Mirror	Good
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	4.5	mm		86	L/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	63	Left Rear	4.0	mm		87	L/F Guard	Good		
10	Rear Reflectors	•	39	Wheel Balance	✓	64	Right Rear	4.5	mm	88	R/F Guard	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	•	65	Spare	Yes	89	L/H Doors	Good				
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	90	R/H Doors	Good				
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable			67	AC Operation	✓	91	L/H Sill	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		68	Heater Fan	✓	92	R/H Sill	Good		
15	Number Plate Light	✓	Brakes		<td>69</td> <td>Seatbelts</td> <td>✓</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>		69	Seatbelts	✓	93	Boot/Tail Gate	Good			
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	70	Horn	✓	94	Front Bumper	Good				
17	Speedo	✓	45	Rear Brakes	✓	71	Seat Heaters	•	95	Rear Bumper	Good				
18	Odometer	✓	46	Handbrake	✓	72	Sun Visors	✓	96	Roof	Good				
19	Rev Counter	✓	Keys and Locking		<td>73</td> <td>Sun Visors Lights/Mirrors</td> <td>✓</td> <td>97</td> <td>Bonnet</td> <td>Good</td>		73	Sun Visors Lights/Mirrors	✓	97	Bonnet	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	74	Seats	Good	98	Fuel Cap	✓				
21	Wipers Front/Rear	✓	48	Remote Locking	✓	75	Carpets	Good	99	Mud Flaps	✓				
22	Window Opener FL	✓	49	Number of Keys	2	76	Panels	Good	100	WOF	✓				
23	Window Opener FR	✓	Engine		<td>77</td> <td>Dashboard</td> <td>Good</td> <td colspan="2"></td>		77	Dashboard	Good						
24	Window Opener RL	✓	50	Oil Level	✓										
25	Window Opener RR	✓	51	Smokes and Fumes	✓										
26	Rear View Mirrors	✓	52	Performance	✓										
27	Radio (Basic Test Only)	✓	53	Noise	✓										
28	CD (Basic Test Only)	✓	54	Starter Motor	✓										
29	Boot Open Switch	✓													

Inspected by:	Ca Son Thach	Date:	28 Jan 2020
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--