

Basic Vehicle Condition Guide

Report ID: 20,009,582


Version: 1

Created: 05 Feb 2020

Make: Model: IS250 Lexus **Body Style:** Sedan Year: 2007 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 17 Dec 2020 80,779 Kms 20009582 VIN: 7AT0B00EX19061524 **Next Service:** 90643 km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Eddie Marsters 05 Feb 2020 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|------------------------------|---|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | <i>y y</i> | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | • | | |
| Operation | ~ | | | | |
| Noise | V | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | 1 | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 7 | mm | | |
| Right front | | 7 | mm | | |
| Left rear | | 4 | mm | | |
| Right rear | 4 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | 1 | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | 1 | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | V V V V V V | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 1 | 1 | 1 | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| L | | | | | |

Signature: