

Report ID: 20,010,396 Version: 1 Created: 10 Feb 2020

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2014		HMG923	Reg Expiry:	14 Nov 2020	Engine			1
WoF Expiry:		Odometer:	235,928 Kms	Good No:	20010396	Oil level	~		1
VIN:	MR0HZ22GX0351840(	Next Service:		Service Histor		Smoke & fumes	~		+
					-	Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Dauta hava nat	heen dispersied of	Noise	~		+
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	/endor recommends	Cooling System	·		<u> </u>
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		+
Key:	S	-0	s sc	-01-	S SC	Radiator / Hoses (visual)	~		+
S = scratch	STE			NG G	<u>کھر</u>	Transmission			
D = dent R = rust	S C SC			The		Operation	~		T
PT = paint defe	ect NP	F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		+
C = crack					SC	Clutch	~		
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~		+
* = decals	sc 916			The second	FID SPSC	Wheel bearings	~		1
SC = stone chips W = significant scuffs						Brakes			
w = significan	S D SC		S SC		S D SC	Performance	~		Τ
Rody Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		1
Body Inspection Comments Rust on rear step above towbar. Scratches , stonechips and dents on RR of cab. Roof rack with work and						Tyres (lowest observed tread	depth	of tyre	es)
warning lights fitted. Damage on front bumper. Damage on front end of LH running board.						Left front	3 mm		
Screw holes	s in console. Wear on st	eering wheel.				Right front	2	1	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry					Right rear	3	3	mm	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Average co	ndition.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			_
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Concil						Window winder FR	~		<u> </u>
<u>General Comments</u> Turbo has whine. Gearbox has noise in some gears. Battery is low.					Window winder RL			~	
TUBO HAS WITHE, GEALDOX HAS HOISE IT SOTTE GEALS. DATTERY IS 10W.						Window winder RR			~
Drives ok.						Rear view mirrors	~		-
						Radio (basic test only)	~		-
						CD (basic test only)	~		
						Number of keys	3		T
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Tir	ming Mechanism:	Cambelt	•			Remote locking	~		
-	of Cam Belt Replac		Tes	Kms: 15	3,428	Sat. Nav. (basic test only)			~
LUNCINCE	or cam bert neplac	tinent. I	<b>C</b> 3	13. 13		Reversing camera	~		
Inspected by: Roger King Date: 10 Feb 2020									
· ·	· - •								
I have read	and understood th	is condition a	uide. Name: .			Signature:			