



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,012,533
Version:	1
Created:	09 Feb 2020

Make:	Mazda	Body Style:	Hatchback
Model:	Demio	VIN:	7AT0C12HX20112502
Year:	2015	Odometer:	95,105 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good												
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	✓										
2	Headlights	✓	32	USB Port	✓	56	Performance	✓	80	Front Windscreen (no chips)	Good										
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good										
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓	82	Side Windows (no chips)	Good									
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83	Front Wiper Blades	Good										
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good										
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	4	mm	85	R/H Mirror	Good							
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	4	mm	63	Left Rear	4	mm	86	L/H Mirror	Good					
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	4	mm	65	Spare	N/A	66	Tools	✓	87	L/F Guard	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	66	Tools	✓	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good				
11	Hazard Lights	✓	40	Gearbox (Manual)	✓	Interior		67	AC Operation	✓	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	100	WOF	✓							
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	•
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	69	Seatbelts	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	70	Horn	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	
18	Odometer	✓	46	Handbrake	✓	71	Seat Heaters	•	72	Sun Visors	✓	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	
19	Rev Counter	✓	Keys and Locking		Interior		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	77	Dashboard	Good	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good
20	Fuel Gauge	✓	47	Central Locking	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	81	Back Windscreen (no chips)	Good	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	82	Side Windows (no chips)	Good	
22	Window Opener FL	✓	49	Number of Keys	2	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	✓	83	Front Wiper Blades	Good	
23	Window Opener FR	✓	Engine		Interior		77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good	84	Rear Wiper Blade	Good
24	Window Opener RL	✓	50	Oil Level	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	85	R/H Mirror	Good	
25	Window Opener RR	✓	51	Smokes and Fumes	✓	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	86	L/H Mirror	Good	
26	Rear View Mirrors	✓	52	Performance	✓	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	✓	87	L/F Guard	Good	
27	Radio (Basic Test Only)	✓	53	Noise	✓	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good	88	R/F Guard	Good	
28	CD (Basic Test Only)	✓	54	Starter Motor	✓	78	Under Carriage	Good	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	89	L/H Doors	Good	
29	Boot Open Switch	✓				79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	90	R/H Doors	Good	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	09 Feb 2020
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--