

## **Basic Vehicle Condition Guide**

Report ID: 20,012,960

Version: 1

Created: 05 Feb 2020


Make:MitsubishiModel:GalantBody Style:HatchbackYear:2010Registration:Reg Expiry:

 WoF Expiry:
 19 Sep 2020
 Odometer:
 47,303 Kms
 Good No:
 20012960

 VIN:
 7AT0CJ0JX19000464
 Next Service:
 52,282
 Service History:
 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Front wheel drive

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date: 05 Feb 2020

Name: .....

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
	7	mm
7		mm
7		mm
7		mm
	Yes	
~		
~		
~		
		1
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		
1		
		V
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

Signature: .....