

Report ID: 20,013,443 Version: 1 14 Feb 2020 Created:

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	1997	Registration:	DRY330	Reg Expiry:	17 Apr 2020	Engine	1		<u> </u>
WoF Expiry:	12 Jun 2020	Odometer:	285,229 Kms	Good No:	20013443	Oil level	~		
VIN:	7A88G610706241589	Next Service:	,	Service Histor	V: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta hava nat	harry discover deal and	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SP W	-0	S SD		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SD 6/6			TIN	SD SD	Operation	~		
R = rust PT = paint def				\int	JHH	Noise	~		
C = crack				+	D R PT	Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	ssc 916			- No	ELP SD	Wheel bearings	~		
SC = stone chi		26		10-	¥ —	Brakes	•		
W = significan	t scuffs S D W	-ve	SP SD		SD	Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		+
Body inspection Comments						Tyres (lowest observed tread	-	of tyre	es)
R/F Seat belt stained , Hood lining stained , Rust in Rear Tailgate shut , Rear Boot cover missing, Rear Headrests missing, Front washer hose leaking,									mm
	5.	5,				Right front		.0	mm
						Left rear		.0 .0	mm
Conditions During Rody Inspections Dry						Right rear	-		
Conditions During Body Inspection: Dry						Right rear 9.0 mn Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak low	er engine area,					Suspension performance	~		1
	-					Steering performance	~		
						Shock absorbers	~		+
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Poor					Head lights	~		
	Deer					Tail lights	~		
Carpets	Poor					Indicators	~		+
Panels	Poor					Dashboard warning lights	~		+
						Wipers (front & rear)	~		+
Dashboa	rd Poor					Window winder FL	~		+
	1					Window winder FR	~		1
General Comments						Window winder RL	~		1
/						Window winder RR	~		+
						Rear view mirrors	~		1
						Radio (basic test only)		~	1
						CD (basic test only)		~	1
						Number of keys	1	I	1
Road Conditions During Test Drive: Dry						Central locking		~	<u> </u>
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			V
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						_	1	1	
Inspecte	d by: Chris Buckley					Date: 14 Feb 20	20		

I have read and understood this condition guide.

Name:

Signature: