

Report ID: 20,017,419 Version: 1 21 Feb 2020 Created:

Make:	Honda	Model:	Jazz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	HCT608	Reg Expiry:	19 Nov 2020	Engine			
WoF Expiry:	20 Nov 2020	Odometer:	92,223 Kms	Good No:	20017419	Oil level	~		
VIN:	MRHGP1830DP01055	Next Service:	101000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	S SC SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			10		Operation	~		
R = rust PT = paint defe				í In	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc 916			- AL	D SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S SC SC SC						Performance	~		
		Note <sup>,</sup> som	ne defects & blemishes	s may not be disr		Hand Brake	~		
	pection Comments				layea in the diagram	Tyres (lowest observed tread	-	oftyre	() ()
Stone chip front window									
						Right front	1	-	mm
						Left rear	1	-	mm mm
			_				6.		-
Conditions During Body Inspection: Dry						Right rear	8.9 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Suspension	Yes		
	ody inspection complet	•	<u>eonnents</u>			-			
	buy inspection complet	cu				Suspension performance Steering performance	~		
							~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Mechanism	Timina				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or cam belt keplac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Bailey Michel Date: 21 Feb 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....