



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,019,574
Version:	1
Created:	06 Mar 2020

Make:	Nissan	Body Style:	SUV
Model:	X-Trail	VIN:	7AT0DH6LX20000177
Year:	2007	Odometer:	95,770 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation				•						
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	84	Rear Wiper Blade	Good	85	R/H Mirror	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>61</td> <td>Left Front</td> <td>7.0</td> <td>mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	60	Shock Absorbers	✓	61	Left Front	7.0	mm	86	L/H Mirror	Good	87	L/F Guard	Good		
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	7.0	mm	63	Left Rear	5.0	mm	88	R/F Guard	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>64</td> <td>Right Rear</td> <td>5.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	64	Right Rear	5.0	mm	65	Spare	Yes	89	L/H Doors	Good	90	R/H Doors	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	66	Tools	✓	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td><td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	
10	Rear Reflectors	•	40	Gearbox (Manual)	•	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th><td>99</td><td>Mud Flaps</td><th>✓</th></th>	69	Seatbelts	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓
11	Hazard Lights	✓ <td>41</td> <td>Engine Timing</td> <td>Timing Chain</td> <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>100</td><td>WOF</td><td>✗</td></th>	41	Engine Timing	Timing Chain	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>100</td> <td>WOF</td> <td>✗</td>	71	Seat Heaters	•	100	WOF	✗						
12	Courtesy Lights	✓ <td>42</td> <td>Evidence of Cam Belt Replacement</td> <td>Not Applicable</td> <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td colspan="3">Turners Certification Key:</td></th></th>	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td colspan="3">Turners Certification Key:</td></th>	73	Sun Visors Lights/Mirrors	✓ <td colspan="3">Turners Certification Key:</td>	Turners Certification Key:								
13	Dashboard Lights	✓ <td>43</td> <td>Replaced at (odometer reading)</td> <td></td> <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td colspan="3">✓ = Pass</td>	43	Replaced at (odometer reading)		74	Seats	Good	75	Carpets	Good	✓ = Pass								
14	Dashboard Dimmer Switch	✓ <th colspan="2">Brakes</th> <td>44</td> <td>Front Brakes</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td><td colspan="3">✗ = Fail</td></th>	Brakes		44	Front Brakes	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td colspan="3">✗ = Fail</td>	76	Panels	Good	77	Dashboard	Good	✗ = Fail						
15	Number Plate Light	✓ <td>45</td> <td>Rear Brakes</td> <th>✓<td>46</td><td>Handbrake</td><th>✓<td colspan="6">• = Not applicable for this vehicle</td></th></th>	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td colspan="6">• = Not applicable for this vehicle</td></th>	46	Handbrake	✓ <td colspan="6">• = Not applicable for this vehicle</td>	• = Not applicable for this vehicle											
16	Dashboard Warning Lights	✓ <th colspan="2">Keys and Locking</th> <td>47</td> <td>Central Locking</td> <th>✓<td colspan="6"></td></th>	Keys and Locking		47	Central Locking	✓ <td colspan="6"></td>													
17	Speedo	✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>49</td><td>Number of Keys</td><td>1</td><td colspan="6"></td></th>	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td colspan="6"></td>	49	Number of Keys	1												
18	Odometer	✓ <th colspan="2">Engine</th> <td>50</td> <td>Oil Level</td> <th>✓<td colspan="6"></td></th>	Engine		50	Oil Level	✓ <td colspan="6"></td>													
19	Rev Counter	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td colspan="6"></td></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td colspan="6"></td></th>	52	Performance	✓ <td colspan="6"></td>												
20	Fuel Gauge	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓<td colspan="6"></td></th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td colspan="6"></td></th>	54	Starter Motor	✓ <td colspan="6"></td>												
21	Wipers Front/Rear	✓ <td colspan="5"></td> <td colspan="6"></td>																		
22	Window Opener FL	✓ <td colspan="5"></td> <td colspan="6"></td>																		
23	Window Opener FR	✓ <td colspan="5"></td> <td colspan="6"></td>																		
24	Window Opener RL	✓ <td colspan="5"></td> <td colspan="6"></td>																		
25	Window Opener RR	✓ <td colspan="5"></td> <td colspan="6"></td>																		
26	Rear View Mirrors	✓ <td colspan="5"></td> <td colspan="6"></td>																		
27	Radio (Basic Test Only)	✓ <td colspan="5"></td> <td colspan="6"></td>																		
28	CD (Basic Test Only)	✓ <td colspan="5"></td> <td colspan="6"></td>																		
29	Boot Open Switch	✓ <td colspan="5"></td> <td colspan="6"></td>																		

Inspected by:	Ca Thach	Date:	13 Feb 2020
---------------	----------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--