

Report ID: 20,020,958 Version: 3 02 Jun 2020 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Wagon | | Pass | Fail | N/A | |
|--|------------------------|---------------|------------------------|-----------------|--|-----------------------------|----------|------------|----------|--|
| Year: | 2008 | Registration: | ERN821 | Reg Expiry: | 20 Sep 2020 | Engine | | | I | |
| WoF Expiry: | 06 Mar 2021 | Odometer: | 233,410 Kms | Good No: | 20020958 | Oil level | ~ | | | |
| VIN: | 6G1EK85719L222722 | Next Service: | | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | - | | - | Performance | ~ | | | |
| | port is not a warranty | | с I I | D | | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | | |
| | | | | | | Performance | ~ | | | |
| Key: | S | -0 | S S | | S | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent SSC 66 | | | | | | Operation 🖌 | | | | |
| R = rust | | | | 10 | THIA | Noise | ~ | | | |
| PT = paint def C = crack | | | | + | | Clutch | V | | ~ | |
| P = pin dent | Ho | KI | | | JUII —— | CV joints | ~ | | V | |
| * = decals | - MIK | | | AL- | ENR | Wheel bearings | | | | |
| SC = stone chips | | | | | | Brakes | J | | | |
| W = significant scuffs S S S S S | | | | | | | | | | |
| | | Notor con | | | | Performance | ~ | | | |
| Body Insp | pection Comments | Note: som | ne defects & blemishes | may not be disp | hayed in the diagram | Hand Brake | ~ | <i>C</i> . | <u> </u> | |
| | | | | | Tyres (lowest observed tread depth of tyres) | | | | | |
| | | | | | | Left front | 8. | | mm | |
| | | | | | | Right front | 8. | | mm | |
| r | | | | | | Left rear | 8. | 0 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 8.0 mm | | | |
| | | | | | | Spare | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| Steering pe | | | | | | | ~ | | | |
| Shoc | | | | | | | ~ | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| Interior Commonts | | | | | | Operation 🖌 | | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| Carpote | Good | | | | | Tail lights | ~ | | | |
| Carpets | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| | Good | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | iu | | | | | Window winder FL | ~ | | | |
| | | | | | | Window winder FR | 5 | | | |
| General Comments | | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | | |
| | | | • | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ | |
| L | | | | | | | | | | |
| Inspected by: Dion Mair Date: 20 Feb 2020 | | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: