



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,218,664
Version:	2
Created:	28 May 2021

Make:	Mitsubishi	Body Style:	People Mover
Model:	Delica	VIN:	7AT0CJ0PX19021855
Year:	2007	Odometer:	91,587 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	Exterior		
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	•	
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good	
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	
4	High Stop Light	✓	Transmission and Drive		Suspension		82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	84	Rear Wiper Blade	Good	
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	85	R/H Mirror	Good	
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	86	L/H Mirror	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	Wheels and Tyres		87	L/F Guard	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	61	Left Front	7.0	mm	88	R/F Guard	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	62	Right Front	7.0	mm	89	L/H Doors	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	✓	63	Left Rear	8.0	mm	90	R/H Doors	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	64	Right Rear	8.0	mm	91	L/H Sill	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes	92	R/H Sill	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		66	Tools	✓	93	Boot/Tail Gate	Good	
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	94	Front Bumper	Good
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	95	Rear Bumper	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	96	Roof	Good	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	97	Bonnet	Good	
19	Rev Counter	✓	Keys and Locking		71	Seat Heaters	•	98	Fuel Cap	✓		
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	99	Mud Flaps	✓	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	100	WOF	✓	
22	Window Opener FL	✓	49	Number of Keys	1	74	Seats	Average				
23	Window Opener FR	✓	Engine		75	Carpets	Average					
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Average				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Good				
26	Rear View Mirrors	✓	52	Performance	✓							
27	Radio (Basic Test Only)	✓	53	Noise	✓							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓							
29	Boot Open Switch	✓										

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	27 Jan 2021
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--