

Report ID: 20,219,675 Version: 1 21 Feb 2020 Created:

Make:	Honda	Model:	Accord	Body Style:	Wagon		Pass	Fail	N//
lear:	1994	Registration:		Reg Expiry:	01 May 2020	Engine			
VoF Expiry:	23 Mar 2020	Odometer:	203,455 Kms	Good No:	20219675	Oil level	~		
/IN:	7A88G13070540716		,	Service Histor		Smoke & fumes	~		
			<u> </u>		. 110	Performance	~		+
	port is not a warrant					Noise	~		+
This report is diagnostic te	s a guide only. Consi sting undertaken. The	deration is made e vehicle has beer	for age and mileag driven up to 50km	je. Parts have not /h from cold. The	been dismantled or /endor recommends	Cooling System	V		_
full mechar	nical inspection prior	to purchase and t	his can be arranged	for an additional o	harge.	Coolant condition			Т
						Performance	~		
Key:	S SC	s o	S SC S SC	S	S SC		~		
= scratch		20	Â	5000	~	Radiator / Hoses (visual)	~		
= dent	SDCSC				ALL SDCSC	Transmission			
= rust				10	SHIK	Operation	~		+
T = paint def	ect M				S PT SC	Noise	~		-
= crack = pin dent	LH					Clutch			~
= pin dent = decals	SDSC 0				I SDSC	CV joints	~		
C = stone chi	ips - Vi			10		Wheel bearings	~		
/ = significan	t scuffs	(0)		$\leq (Q) \geq$		Brakes			—
	S D SC	s	S SC S SC	S	S	Performance	~		
Body Ins	pection Comment	Note: son	ne defects & blemish	es may not be disp	layed in the diagram	Hand Brake	~		
Roof-bonne	et-paint faded,panels i	missing from the r	oof rack,minor stone	chips in the winds	creen ,	Tyres (lowest observed tread depth of tyres)			
						Left front	5	5	mr
						Right front	5	5	mr
						Left rear	6	5	mr
Conditions During Body Inspection: Dry						Right rear	e	5	mr
,						Spare		Yes	
<u>Under Ca</u>	arriage & Under Bo	onnet Inspectio	on Comments			Suspension			
Minor oil le	ak ,car needs a service	· ,				Suspension performance	~		
						Steering performance	V		
						Shock absorbers	~		1
						Air Conditioning / Heater	1		4
						Operation		~	Τ
Interior C	<u>Comments</u>					Electrical / Accessories	1		
Seats	wear and	d tear,minor stains	,			Head lights	~		Γ
	wearan	d tear,minor stains				Tail lights	~		+
Carpets	wear and		,			Indicators	~		+
Panels	Average					Dashboard warning lights	~		+
						Wipers (front & rear)	~		+
Dashboa	ard Average					Window winder FL	~		+
	I					Window winder FR	~		+
<u>Gene</u> ral (<u>Comments</u>					Window winder RL	~		+
	elts when you turn the	air con on ,				Window winder RR	~		+
						Rear view mirrors	~		+-
						Radio (basic test only)			+
							v		_
						CD (basic test only)	v		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		-
Road Con	ming Mechanism	Cambel	t			Remote locking Sat. Nav. (basic test only)			~
									V
Engine Ti	-			17					1 .
Engine Ti	of Cam Belt Repla	icement: N	lo	Kms:		Reversing camera			~
Engine Ti Evidence	-		lo	Kms:		Reversing camera Date: 21 Feb 20	20		

I have read and understood this condition guide.

Name:

Signature: