

Report ID: 20,220,441 Version: 2 26 Feb 2020 Created:

Make:	Toyota	Model:	Prius	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2013	<b>Registration:</b>	MSL778	Reg Expiry:	18 Aug 2020	Engine	1		I	
WoF Expiry:	05 Dec 2020	Odometer:	113,386 Kms	Good No:	20220441	Oil level	~			
VIN:	7AT0H637X19685972	Next Service:	123000	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust						Operation	Operation 🖌			
PT = paint defe		r I		$\left( \left  \left( \right) \right\rangle \right)$	7014	Noise	~			
C = crack						Clutch			~	
P = pin dent	HIG				74116	CV joints	~			
*= decals						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv – signincan			S			Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments LH wing mirror damaged						Tyres (lowest observed tread depth of tyres)				
surface stone chips on windscreen						Left front	4.	.5	mm	
						Right front	4.	.5	mm	
						Left rear	4.	.5	mm	
Conditions During Body Inspection: Wet						Right rear	4.	4.5 mm		
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Front whee	l drive					Suspension performance	~			
						Steering performance	۲			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
Engine Ti	ning Machanism	Timina	Chain			Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	or Cam Bert Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	d by: Xinghui Lin					Date: 25 Feb 20	20			

I have read and understood this condition guide.

Name: .....