



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,223,722
Version:	1
Created:	24 Feb 2020

Make:	Nissan	Body Style:	Hatchback
Model:	Leaf	VIN:	7AT0DH8KX20106252
Year:	2014	Odometer:	56,923 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58 <td>Suspension Performance</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	Suspension Performance	✓	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34 <td>Operation</td> <th>✓</th> <td>59</td> <td>Steering Performance</td> <th>✓</th> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	Operation	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7.4	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	7.4	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	5.1	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	6.5	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	✓	65	Spare	Yes	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67 <td>AC Operation</td> <th>✓</th> <td>92</td> <td>R/H Sill</td> <td>Good</td>	AC Operation	✓	92	R/H Sill	Good	
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44 <td>Front Brakes</td> <th>✓</th> <td>69</td> <td>Seatbelts</td> <th>✓</th> <td>94</td> <td>Front Bumper</td> <td>Good</td>	Front Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓	70	Horn	✓	71	Seat Heaters	✓	95	Rear Bumper	Good
16	Dashboard Warning Lights	✓	46	Handbrake	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	96	Roof	Good
17	Speedo	✓	Keys and Locking		47 <td>Central Locking</td> <th>✓</th> <td>74</td> <td>Seats</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	Central Locking	✓	74	Seats	Good	97	Bonnet	Good	
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	1	75	Carpets	Good	98	Fuel Cap	✓
19	Rev Counter	✓	Engine		50 <td>Oil Level</td> <th>✓</th> <td>76</td> <td>Panels</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	Oil Level	✓	76	Panels	Good	99	Mud Flaps	✓	
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓	77	Dashboard	Good	100	WOF	✗
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓	Turners Certification Key:					
22	Window Opener FL	✓			✓ = Pass									
23	Window Opener FR	✓			✗ = Fail									
24	Window Opener RL	✓			• = Not applicable for this vehicle									
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

Inspected by:	Ian Dunn	Date:	24 Feb 2020
I have read and understood this condition guide:			
Name:		Signature:	