



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,226,647
Version:	1
Created:	16 Mar 2020

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00175193
Year:	2009	Odometer:	72,368 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•			
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		Suspension		82	Side Windows (no chips)	Good					
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good			
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres					
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	5	mm	86	L/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	6	mm	87	L/F Guard	Good		
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	6	mm	88	R/F Guard	Good		
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	6	mm	89	L/H Doors	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	90	R/H Doors	Good			
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	91	L/H Sill	Good			
14	Dashboard Dimmer Switch	•	43	Replaced at (odometer reading)		Interior		67	AC Operation	✓	92	R/H Sill	Good	
15	Number Plate Light	✓	Brakes		44	Front Brakes	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good	
16	Dashboard Warning Lights	✓	45	Rear Brakes	✓	46	Handbrake	✓	69	Seatbelts	✓	94	Front Bumper	Good
17	Speedo	✓	Keys and Locking		47	Central Locking	✓	70	Horn	✓	95	Rear Bumper	Good	
18	Odometer	✓	48	Remote Locking	✓	49	Number of Keys	2	71	Seat Heaters	•	96	Roof	Good
19	Rev Counter	✓	49	Number of Keys	2	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	97	Bonnet	Good
20	Fuel Gauge	✓	Engine		50	Oil Level	✓	74	Seats	Good	98	Fuel Cap	✓	
21	Wipers Front/Rear	✓	51	Smokes and Fumes	✓	52	Performance	✓	75	Carpets	Good	99	Mud Flaps	✓
22	Window Opener FL	✓	53	Noise	✓	54	Starter Motor	✓	76	Panels	Good	100	WOF	✓
23	Window Opener FR	✓							77	Dashboard	Good			
24	Window Opener RL	✓												
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	16 Mar 2020
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--