

## **Basic Vehicle Condition Guide**

Report ID: 20,228,023

Pass

1

1

/

V

1

Version:

Engine

Oil level

Noise

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Operation

Head lights Tail lights Indicators

Spare

Smoke & fumes

Performance

Cooling System

Created: 07 Mar 2020

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

4.0

4.0

4.0

4.0

1

/

/


1

Yes

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2009 Registration: FBJ715 **Reg Expiry:** 10 Sep 2020 WoF Expiry: **Odometer:** 13 Mar 2021 303,381 Kms **Good No:** 20228023 VIN: MR0FZ29G601563559 Next Service: 313390 **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

**General Comments** 

Radio (basic test only) 1 CD (basic test only) 1 Number of kevs 1

Road Conditions During Test Drive: Dry	Central locking	<b>V</b>		
	Remote locking	V		
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: No	Reversing camera		~	
Inspected by: Dion Mair	Date: 02 Mar 2020			
I have read and understood this condition guide.	Name:	Signature:		