

Report ID: 20,230,020 Version: 1 01 Mar 2020 Created:

Signature:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013		HFG152	Reg Expiry:	26 Mar 2020	Engine			
	14 Jan 2021	Odometer:	126,918 Kms	Good No:	20230020	Oil level	~		
VIN:	KMFWBX7KLEU60616			Service Histor		Smoke & fumes	~		
			137,000			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Cooling System Coolant condition			
		_				Performance	~		
Key:		-0	ls			Radiator / Hoses (visual)	~		
S = scratch	Se	20		10/2	\mathbf{x}	Transmission	V		
D = dent	Alt			1 - L	BID	Operation	~		
R = rust				10		Noise	~		
PT = paint defe C = crack	ect M			+		Clutch	-		
P = pin dent	Ho					CV joints	~		
* = decals	DIAIR			AL-	Ell'As	Wheel bearings			~
SC = stone chips							Wheel bearings		
W = significant scuffs									
		Notorcom				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~)
Remotes not working						Tyres (lowest observed tread depth of tyres)			
Far tyre inner edge wear LH headlamp low beam not working						Left front		.5	mm
Rear wiper washer not working						Right front		5 m	
						Left rear	<u> </u>		mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	inet inspectic	<u>In comments</u>			Suspension		1	1
Rear wheel Engine oil le						Suspension performance	~		
-						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Good						lectrical / Accessories			
Seats						Head lights		~	
Carpets	Good					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	i	1
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
		T' '				Remote locking		~	
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Mathew Varghese Date: 01 Mar 2020									

I have read and understood this condition guide.

Name: