

Basic Vehicle Condition Guide

Report ID: 20,239,651

Pass

Version: 3

Engine

Created: 07 May 2020


Fail

N/A

Make: Model: Holden Malibu **Body Style:** Sedan Year: 2014 Registration: HMZ491 Reg Expiry: 01 Oct 2020 WoF Expiry: **Odometer:** 21 May 2021 152,852 Kms **Good No:** 20239651 VIN: KL3GA6919DB038328 Next Service: 160000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

Oil level	~			
Smoke & fumes	~			
Performance	V V			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
ransmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	;	7	mm	
Right front	7	7	mm	
Left rear	4		mm	
Right rear	5		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\triangle \)			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

I have read and understood this condition guide.

Mathew Varghese

Name:

Signature:

07 May 2020

Date: