

Report ID: 20,239,928 Version: 1 02 Mar 2020 Created:

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	GBK516	Reg Expiry:	25 Mar 2021	Engine			I
WoF Expiry:	11 Oct 2020	Odometer:	142,071 Kms	Good No:	20239928	Oil level	~		
VIN:	JSAGYB51S00302842	Next Service:	149,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	<u>s</u>			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			I
D = dent R = rust	s sc			715	HILLS	Operation	~		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74114	CV joints	~		
* = decals	sc 916					Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	5.	1	mm	
						Right front	5.	6	mm
						Left rear	5.	2	mm
Conditions During Body Inspection: Dry						Right rear	2.4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Darkle	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
F ar at 1 = 7 ¹		T' '				Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 28 Feb 2020									
Inspected by, Sason Foung Date: 20 Feb 2020									

I have read and understood this condition guide.

Name:

Signature: