

Report ID: 20,251,871 Version: 2 20 Mar 2020 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	KUW875	Reg Expiry:	28 Jun 2020	Engine			L
WoF Expiry:		Odometer:	6,384 Kms	Good No:	20251871	Oil level	~		
VIN:	MNTCB4D23A003173	Next Service:	20,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			The		Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent					741L	CV joints	~		
* = decals	616			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$-\omega$	S		s	Performance	~		
		Note: som	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments					Tyres (lowest observed tread	•	of tyre	<u>ا</u>
						Left front	6.	,	 
						Right front	6.		 mm
						Left rear		-	mm
Conditions During Rodulnsnostion.						Right rear	0.0		 mm
Conditions During Body Inspection: Dry						Spare	0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
4WD		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Denela	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FE	<i>v</i> <i>v</i>		
General Comments						Window winder RL	~		
						Window winder RL	<i>v</i> <i>v</i>		
						Rear view mirrors	<i>v</i> <i>v</i>		
						Radio (basic test only)	~		
						CD (basic test only)			
						Number of keys	~		<u> </u>
							2		
Road Conditions During Test Drive: Dry						Central locking	<b>v</b>		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
						Reversing camera	~		<u> </u>
Inspected by: Ca Thach Date: 20 Mar 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....