

I have read and understood this condition guide.

Report ID: 20,252,920 Version: 1 19 Mar 2020 Created:

Signature:

Make:	Suzuki	Model:	SX4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	EMY53	Reg Expiry:	09 Sep 2020	Engine			
WoF Expiry:	14 Jan 2021	Odometer:	132,930 Kms	Good No:	20252920	Oil level	~		
VIN:	JSAGYA41S00110925	Next Service:	141350	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		S D SC S P SC		S D	Performance	~		
Key:	La C	-0	3030 3730		30	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				710	HIVS	Operation	~		
PT = paint defe	ect NP	r I		$\left(\left \left(\right) \right\rangle \right)$	701/1	Noise	~		
C = crack					SC	Clutch	r		
P = pin dent	HE				7414	CV joints	~		
* = decals	sc 816				AID'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC S SC P SC						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread depth of tyres)			
Minor stone chips in the windscreen ,						Left front 5 mm			
						Right front	6		mm
						Left rear		5	mm
Condition	as During Body Ins	nection:	Day			Right rear		5	mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	· ·		
			Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	-								-
Inspected by: Donovan Matara Date: 19 Mar 2020									

Name: