



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,259,621
Version:	2
Created:	16 Mar 2020

Make:		Body Style:	
Model:		VIN:	7AT0H637X20030512
Year:		Odometer:	89,083 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good						
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td colspan="2">Wheels and Tyres</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <td colspan="2">Wheels and Tyres</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good						
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.5 mm	86	L/H Mirror	Good								
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>5.5 mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	5.5 mm	87	L/F Guard	Good								
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>6.0 mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	6.0 mm	88	R/F Guard	Good								
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6.0 mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	6.0 mm	89	L/H Doors	Good								
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	N/A	90	R/H Doors	Good								
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good								
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	69	Seatbelts	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good					
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	71	Seat Heaters	•	94	Front Bumper	Good			
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th></th>	46	Handbrake	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good		
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	96	Roof	Good			
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	2	76	Panels	Good	77	Dashboard	Good	97	Bonnet	Good		
18	Odometer	✓	Engine		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th>	53	Noise	✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>	98	Fuel Cap	✓
19	Rev Counter	✓	54	Starter Motor	✓ <td colspan="12"></td>														
20	Fuel Gauge	✓																	
21	Wipers Front/Rear	✓ <td colspan="14"></td>																	
22	Window Opener FL	✓ <td colspan="14"></td>																	
23	Window Opener FR	✓ <td colspan="14"></td>																	
24	Window Opener RL	✓ <td colspan="14"></td>																	
25	Window Opener RR	✓ <td colspan="14"></td>																	
26	Rear View Mirrors	✓ <td colspan="14"></td>																	
27	Radio (Basic Test Only)	✓ <td colspan="14"></td>																	
28	CD (Basic Test Only)	✓ <td colspan="14"></td>																	
29	Boot Open Switch	✓ <td colspan="14"></td>																	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	14 Mar 2020
---------------	----------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--