



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,259,792
Version:	2
Created:	25 Sep 2020

Make:	Nissan	Body Style:	Hatchback
Model:	Leaf	VIN:	7AT0DH8KX20121708
Year:	2015	Odometer:	53,640 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good										
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•												
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good													
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good											
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good											
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	60	Shock Absorbers	✓	83	Front Wiper Blades	Good													
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	5.0	mm	84	Rear Wiper Blade	Good										
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>5.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>4.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	5.0	mm	63	Left Rear	4.0	mm	85	R/H Mirror	Good								
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>4.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>No</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	4.0	mm	65	Spare	No	86	L/H Mirror	Good									
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good													
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	88	R/F Guard	Good											
11	Hazard Lights	✓	41	Engine Timing	Unknown	68	Heater Fan	✓	69	Seatbelts	✓	89	L/H Doors	Good										
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	✓	90	R/H Doors	Good										
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	91	L/H Sill	Good										
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	74	Seats	Good	75	Carpets	Average	92	R/H Sill	Good								
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	76	Panels	Good	77	Dashboard	Good	93	Boot/Tail Gate	Good							
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	78	Fuel Cap	✓	94	Front Bumper	Good	95	Rear Bumper	Good								
17	Speedo	✓	48	Remote Locking	✓	49	Number of Keys	2	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓							
18	Odometer	✓	Engine		50	Oil Level	•	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓					
19	Rev Counter	•	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓				
20	Fuel Gauge	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓				
21	Wipers Front/Rear	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓				
22	Window Opener FL	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓				
23	Window Opener FR	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓				
24	Window Opener RL	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm			
25	Window Opener RR	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm		
26	Rear View Mirrors	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	4.0	mm	
27	Radio (Basic Test Only)	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	4.0	mm	64	Right Rear	4.0	mm
28	CD (Basic Test Only)	✓	60	Shock Absorbers	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	4.0	mm	64	Right Rear	4.0	mm	65	Spare	No
29	Boot Open Switch	✓	61	Left Front	5.0	mm	62	Right Front	5.0	mm	63	Left Rear	4.0	mm	64	Right Rear	4.0	mm	65	Spare	No	66	Tools	✓

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	18 Mar 2020
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--