

Report ID: 20,268,242 Version: 1 20 Mar 2020 Created:

Make:	Toyota	Model:	Estima	Body Style:	Wagon		Pass	Fail	N/A
Year:	2000	Registration:	GEN351	Reg Expiry:	18 Jul 2020	Engine			
WoF Expiry:	19 Mar 2020	Odometer:	180,156 Kms	Good No:	20268242	Oil level	~		
VIN:	7AT0H61YX11064087	Next Service:	160000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta harra nat	haan diamaanda daar	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	sc	-0	PT W D PT W		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT SC W			The	PT W	Operation	~		
R = rust PT = paint def				r In	THA	Noise	~		
C = crack				+	╫╫╢	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	PT SC PIE			The	EITR S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs DW W DSC SPTW W W						Performance	~		
		Note: som				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								ofturo))
Front bumper alignment left side Both front tyres outer edge wear						Tyres (lowest observed tread depth of tyres) Left front 2			
Front bumper mounting broken						Right front	2		mm
							2		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Gearbox oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Drivers seat worn						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concret	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Machanism	Timine	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 20 Mar 2020									

I have read and understood this condition guide.

Name:

Signature: