



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,271,266
Version:	3
Created:	27 Nov 2020

Make:	Nissan	Body Style:	SUV
Model:	Elgrand	VIN:	7AT0DH6MX19005469
Year:	2010	Odometer:	126,938 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	Exterior			
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	•		
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good		
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓	82	Side Windows (no chips)	Good	
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83	Front Wiper Blades	Good		
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		85	R/H Mirror	Good			
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	4.0	mm	86	L/H Mirror	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	4.0	mm	87	L/F Guard	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	5.0	mm	88	R/F Guard	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	5.0	mm	89	L/H Doors	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	No	90	R/H Doors	Good		
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	91	L/H Sill	Good		
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		67	AC Operation	✓	92	R/H Sill	Good
15	Number Plate Light	✓	Brakes		Interior		68	Heater Fan	✓	93	Boot/Tail Gate	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good		
17	Speedo	✓	45	Rear Brakes	✓	70	Horn	✓	95	Rear Bumper	Good		
18	Odometer	✓	46	Handbrake	✓	71	Seat Heaters	•	96	Roof	Good		
19	Rev Counter	✓	Keys and Locking		72	Sun Visors	✓	97	Bonnet	Good			
20	Fuel Gauge	✓	47	Central Locking	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓		
21	Wipers Front/Rear	✓	48	Remote Locking	✓	74	Seats	Good	99	Mud Flaps	✓		
22	Window Opener FL	✓	49	Number of Keys	2	75	Carpets	Good	100	WOF	✓		
23	Window Opener FR	✓	Engine		76	Panels	Good	Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle					
24	Window Opener RL	✓	50	Oil Level	✓	77	Dashboard				Good		
25	Window Opener RR	✓	51	Smokes and Fumes	✓								
26	Rear View Mirrors	✓	52	Performance	✓								
27	Radio (Basic Test Only)	✓	53	Noise	✓								
28	CD (Basic Test Only)	✓	54	Starter Motor	✓								
29	Boot Open Switch	✓											

Inspected by:	John Lindsay	Date:	16 Jun 2020
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--