

Report ID: 20,275,099 Version: 1 02 Jun 2020 Created:

Make:	Honda	Model:	Stepwagon	Body Style: Wagon] [Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:	Engine	I	L	I
WoF Expiry:		Odometer:	102,543 Kms	Good No: 20275099	Oil level	~		
VIN:	7AT08G87X20211938	Next Service:		Service History: No	Smoke & fumes	~		
					Performance	~		
	port is not a warranty		< L		Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						•		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition			
		_			Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch					Transmission			
D = dent					Operation 🖌			
R = rust					Noise		~	
PT = paint defe C = crack	ect III		-		Clutch		V	~
P = pin dent	Ho				CV joints	~		
* = decals	- MIK				Wheel bearings			
SC = stone chips					Wheel bearings			
W = significant scuffs					Performance			
		Note: com			Hand Brake	レ レ		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						· ·	ofture	
					Tyres (lowest observed tread depth of tyres)			
					Left front	8 mm		
					Right front		8 mm	
					Left rear	8 mm		
Conditions During Body Inspection: Dry					Right rear	8 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare			
	inage & onder bor	inet inspectic	in comments		Suspension			
					Suspension performance	~		
					Steering performance	~		
Shock absorbers						~		
					Air Conditioning / Heater			
Interior Comments					Operation 🖌			
Good					Electrical / Accessories			
Seats	0000				Head lights	~		
Carpets	Good				Tail lights	~		
	Good				Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dashboa	Good Good				Wipers (front & rear)	~		
					Window winder FL	~		
Concert	ommorte				Window winder FR	~		
<u>General Comments</u> Transmission noisey on road test					Window winder RL	~		
	in holsey of rodu test				Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)	~		
Number of keys						1	1	
Road Conditions During Test Drive: Dry Central locking								
Remote locking						~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera	~		
Inspected by: Bobby Zhong Date: 02 Jun 2020								

I have read and understood this condition guide.

Name:

Signature: