



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,291,239
Version:	2
Created:	28 May 2020

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00375003
Year:	2011	Odometer:	52,560 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good				
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good				
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good					
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good					
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good					
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7.0	mm	86	L/H Mirror	Good						
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>7.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	7.0	mm	87	L/F Guard	Good						
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	7.0	mm	88	R/F Guard	Good						
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	7.0	mm	89	L/H Doors	Good						
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	Yes	66	Tools	✓	90	R/H Doors	Good				
11	Hazard Lights	✓	41	Engine Timing	Timing Chain							91	L/H Sill	Good				
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable							92	R/H Sill	Good				
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		Brakes		Interior		67	AC Operation	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓			44	Front Brakes	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th></th>	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>	69	Seatbelts	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good		
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	46	Handbrake	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>95</td><td>Rear Bumper</td><td>Good</td></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	71	Seat Heaters	•	95	Rear Bumper	Good	
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>96</td> <td>Roof</td> <td>Good</td>	96	Roof	Good		
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	1	74	Seats	Good	75	Carpets	Good	97	Bonnet	Good	
18	Odometer	✓			Engine		50	Oil Level	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	76	Panels	Good	77	Dashboard	Good	98	Fuel Cap	✓
19	Rev Counter	•	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>54</td><td>Starter Motor</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	54	Starter Motor	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓	
20	Fuel Gauge	✓	53	Noise	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td>100</td> <td>WOF</td> <th>✓</th>									100	WOF	✓		
21	Wipers Front/Rear	✓																
22	Window Opener FL	✓																
23	Window Opener FR	✓																
24	Window Opener RL	✓																
25	Window Opener RR	✓																
26	Rear View Mirrors	✓																
27	Radio (Basic Test Only)	✓																
28	CD (Basic Test Only)	✓																
29	Boot Open Switch	✓																

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Dante Dacanay	Date:	15 May 2020
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--