



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	20,292,376
Version:	1
Created:	25 May 2020

Make:	Mazda	Body Style:	SUV
Model:	Premacy	VIN:	7AT0C133X20342208
Year:	2009	Odometer:	86,811 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good									
1	Battery	✓	31	Reversing Camera	✓	55	Coolant Condition	✓	79	Sun Roof Operation	•							
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good							
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good							
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓	82	Side Windows (no chips)	Good						
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83	Front Wiper Blades	Good							
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good							
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	5.0	mm	85	R/H Mirror	Good				
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	5.0	mm	63	Left Rear	6.0	mm	86	L/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	6.0	mm	65	Spare	Yes	87	L/F Guard	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	66	Tools	✓	88	R/F Guard	Good	89	L/H Doors	Good				
11	Hazard Lights	✓	40	Gearbox (Manual)	✓	Interior		67	AC Operation	✓	90	R/H Doors	Good	91	L/H Sill	Good		
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	69	Seatbelts	✓	92	R/H Sill	Good	93	Boot/Tail Gate	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓	71	Seat Heaters	•	94	Front Bumper	Good	95	Rear Bumper	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	96	Roof	Good	97	Bonnet	Good	
15	Number Plate Light	✓	Brakes		Interior		74	Seats	Good	75	Carpets	Good	98	Fuel Cap	✓	99	Mud Flaps	✓
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	76	Panels	Good	77	Dashboard	Good	100	WOF	✓				
17	Speedo	✓	45	Rear Brakes	✓													
18	Odometer	✓	46	Handbrake	✓													
19	Rev Counter	✓	Keys and Locking															
20	Fuel Gauge	✓	47	Central Locking	✓ <td colspan="7"></td>													
21	Wipers Front/Rear	✓	48	Remote Locking	✓ <td colspan="7"></td>													
22	Window Opener FL	✓	49	Number of Keys	2													
23	Window Opener FR	✓	Engine															
24	Window Opener RL	✓	50	Oil Level	✓ <td colspan="7"></td>													
25	Window Opener RR	✓	51	Smokes and Fumes	✓ <td colspan="7"></td>													
26	Rear View Mirrors	✓	52	Performance	✓ <td colspan="7"></td>													
27	Radio (Basic Test Only)	✓	53	Noise	✓ <td colspan="7"></td>													
28	CD (Basic Test Only)	✓	54	Starter Motor	✓ <td colspan="7"></td>													
29	Boot Open Switch	✓ <td colspan="2"></td> <td colspan="7"></td>																

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	19 May 2020
I have read and understood this condition guide:			
Name:		Signature:	