

Report ID: 20,298,185 Version: 1 28 May 2020 Created:

Make:	Suzuki	Model:	SX4	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011	Registration:	KHG518	Reg Expiry:	29 Jun 2020	Engine			
WoF Expiry:		Odometer:	120,577 Kms	Good No:	20298185	Oil level	~		
VIN:	7AT0GKG7X16300574	Next Service:	125000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			D		S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				710	BUSDW	Operation	~		
PT = paint defe	ect NP				17111	Noise	~		
C = crack						Clutch			~
P = pin dent	s dR				74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			PT PT P		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			s)
						Left front	6	5	mm
						Right front	7	,	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry Right rear							6	5	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / Heater									
Operation									
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							20		
Inspected by: Bobby Zhong Date: 28 May 2020									

I have read and understood this condition guide.

Name:

Signature: