

Report ID: 20,313,273 Version: 2 22 Jun 2020 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility			Pass	Fail	N/A	
Year:	2011	Registration:	FWG517	Reg Expiry: 28 Jul 2020			Engine			1	
WoF Expiry:	26 May 2021	Odometer:	171,530 Kms	Good No:	20313273	Oil level		~			
VIN:	MNALSFE90BW93118	Next Service:	185000	Service Histor	y: No	Smoke &	fumes	~			
						Performa	nce	v			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition				
						Performa	nce	~			
Key:	S SC	-0	S D SC S D R SC	-161-	SDR		/ Hoses (visual)	~			
S = scratch							Transmission				
D = dent	s sc			TIN	A S	Operatio	n	~			
R = rust PT = paint def				\prod	1711A	Noise		~			
C = crack				+	R SC	Clutch		~			
P = pin dent					세비	CV joints		~			
* = decals	DSC 916			-NL	ELIP SD	Wheel be		~			
SC = stone chips						Brakes					
W = significant scuffs SC P S D R SC						Performance		~			
		Note: som	ne defects & blemishes	may not be disc	layed in the diagram	Hand Bra		~			
Body Inspection Comments							Tyres (lowest observed tread			<u> </u>	
Rear right mudflap missing Both sills minor damage/scratches										mm	
							Right front				
						Left rear		210		mm	
Canditiana Duvina Dadukana atian						Right rear					
Conditions During Body Inspection: Wet						Spare					
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension					
Rear right tail light lens cracked						Suspension performance					
						· · ·	performance	v v			
								v v			
						Air Conditioning / Heater					
Interior Comments						Operation V					
Holes stains						Electrical / Accessories Head lights					
Seats								~			
Carpets	Stains					Tail lights			v		
	Scratches.	rear left winder l	handle damaged			Indicator			~		
Panels							rd warning lights	v			
Dashboa	rd Scratches						ront & rear) winder FL	v			
								v			
General (Comments					L	winder FR	~			
							winder RL	~			
							winder RR	~			
						Rear view		~			
							isic test only)	~			
							test only)	•			
						Number of keys 1					
Road Conditions During Test Drive: Wet						Central lo		~			
Engine Ti	ming Mechanism:	Cambelt				Remote l	-			~	
						Sat. Nav. (basic test only)				~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera				~	
Inspected by: John Lindsay Date: 16 Jun 2020											

I have read and understood this condition guide.

Name:

Signature: