

Basic Vehicle Condition Guide

Report ID: 20,324,816


Version: 1

Created: 22 Jun 2020

Make: Model: Honda Odyssey **Body Style:** Wagon Year: 2004 Registration: HAZ709 Reg Expiry: 31 Aug 2020 WoF Expiry: **Odometer:** 06 May 2021 257,512 Kms **Good No:** 20324816 VIN: 7AT08G61X12063120 **Next Service:** 264,848 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Wheel arch moulding broken and missing Front windscreen has major crack on left side

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

General Comments

Large engine oil leak Front outer rack ends joints loose Brake rotors warn

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 22 Jun 2020

Name:

| | | | 1 | |
|------------------------------|-----------------|---------|-----|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | • | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 4 | .2 | mm | |
| Right front | 4.9 | | mm | |
| Left rear | 6.3 | | mm | |
| Right rear | 5.6 | | mm | |
| Spare | | Yes | | |
| Suspension | • | | | |
| Suspension performance | | ~ | | |
| Steering performance | | ~ | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | | ~ | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | V V V V V V V V | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | | ~ | | |
| CD (basic test only) | | ~ | | |
| Number of keys | 1 | | | |
| Central locking | | ~ | | |
| Remote locking | | | ~ | |
| Sat. Nav. (basic test only) | | | · | |
| Reversing camera | | | ~ | |
| . | | | | |

Signature: