

Report ID: 20,324,837 Version: 1 23 Jun 2020 Created:

Make:	Nissan	Model:	Primera	Body Style:	Sedan			Pass	Fail	N/A	
Year:	1997	Registration:MUS796Reg Expiry:23 Oct 2020		Eng	ine						
WoF Expiry:	03 Aug 2020	Odometer:	135,178 Kms	Good No:	20324837	Oi	llevel	~			
VIN:	7A8DH2G0703537401	Next Service:	141000	Service Histor	y: No	Sm	noke & fumes		~		
						l Pe	Performance		~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Nc	bise		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						C00	Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Co	olant condition	~			
						Pe	rformance	~			
Key: PT S SD S						Ra	Radiator / Hoses (visual)				
S = scratch						Trar	nsmission				
D = dent R = rust PT = paint defect C = crack						Or	Operation		~		
						No	bise		~		
						Clu	utch		-	~	
P = pin dent						CV	/ joints		~	-	
* = decals SC 919 SD							heel bearings	~	-		
SC = stone chips						Bral	-	·			
W = significant scuffs SD S S S S							Performance 🖌				
							Ind Brake	~			
Body inspection Comments							Tyres (lowest observed tread depth of tyres)				
Drivers door hinges worn										mm	
							Right front		-	 mm	
							Left rear		510		
Conditions During Pody Inspection:						- I	Right rear		4.0 mm 5.0 mm		
Conditions During Body Inspection: Dry						<u> </u>	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						11—·	Suspension				
Significant engine oil leaks Power steering fluid leak							spension performance		~		
							eering performance		• •		
							ock absorbers	~	•		
							Conditioning / Heater	v			
						」 ├──	Operation V				
Interior Comments						Electrical / Accessories					
Seats Average						Head lights					
							il lights	~			
Carpets	Average						dicators	~			
Deve alla	Average						ashboard warning lights	~			
Panels								~			
Dashboa	d Average						ipers (front & rear) indow winder FL	•	~		
							indow winder FR	~	~		
General (<u>Comments</u>						indow winder RL				
Cv joints worn							indow winder RE	ン ン			
Engine ratt							ar view mirrors	<i>v</i> <i>v</i>			
							dio (basic test only)	 			
) (basic test only) Imber of keys	1			
Road Conditions During Test Drive: Dry						. —	entral locking	1 •			
Koad Con	ditions During Test	Drive:	Dry				-	~			
Engine Ti	ming Mechanism:	Timing	Chain				mote locking			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							t. Nav. (basic test only)			~	
							versing camera			~	
Inspected by: Greg Morgan Date: 22 Jun 2020											

I have read and understood this condition guide.

Name:

Signature: