

Report ID: 20,328,531


Version: 1

Created: 25 Jun 2020

| Make: | Toyota | Model: | Corolla | Body Style: | Hatchback |
|-------------|-------------------|---------------|-------------|----------------|----------------|
| Year: | 2001 | Registration: | AFH477 | Reg Expiry: | 13 Mar 2021 |
| WoF Expiry: | 22 May 2020 | Odometer: | 290,856 Kms | Good No: | 20328531 |
| VIN: | JT764AEB103106340 | Next Service: | 297200 | Service Histor | r y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chips not in CVA Left front headlight lens chipped

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak Gearbox oil leak Right outer cv boot broken Brakes worn

| Interior | Comments |
|----------|----------|
| | |

| Seats | Squeaking drivers seat |
|-----------|------------------------|
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: Yes Kms:

216,204

Name:

| | Pass | Fail | N/A | | | |
|--|--|------|----------|--|--|--|
| Engine | - | • | • | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | \(\times \) | | | | | |
| Performance | ~ | | | | | |
| Noise | ~ | | | | | |
| Cooling System | • | • | • | | | |
| Coolant condition | ~ | | | | | |
| Performance | ~ | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | V | | | | | |
| Clutch | | | ~ | | | |
| CV joints | ~ | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | | | | | |
| Performance | | ~ | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | |
| Left front | 4 | 4 | mm | | | |
| Right front | 4 | | mm | | | |
| Left rear | | 1 | mm | | | |
| Right rear | 2 | | mm | | | |
| Spare | | Yes | | | | |
| Suspension | | | | | | |
| Suspension performance | V V | | | | | |
| Steering performance | ~ | | | | | |
| Shock absorbers | ~ | | | | | |
| Air Conditioning / Heater | | | | | | |
| Operation | ~ | | | | | |
| Electrical / Accessories | | | | | | |
| Head lights | ~ | | | | | |
| Tail lights | ~ | | | | | |
| Indicators | ~ | | | | | |
| Dashboard warning lights | \(\times \) \(\t | | | | | |
| Wipers (front & rear) | ~ | | | | | |
| Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | ~ | | | | | |
| Window winder RR | ~ | | | | | |
| Rear view mirrors | ~ | | | | | |
| Radio (basic test only) | ~ | | | | | |
| CD (basic test only) | | | ~ | | | |
| Number of keys | 2 | | | | | |
| Central locking | ~ | | | | | |
| Remote locking | ~ | | | | | |
| Sat. Nav. (basic test only) | | | ~ | | | |
| Reversing camera | | | ' | | | |

25 Jun 2020

Signature:

Date: