

Basic Vehicle Condition Guide

Report ID: 20,328,679


Version: 2

Created: 26 Jun 2020

Make: Model: Toyota Corolla **Body Style:** Hatchback Year: 2004 Registration: HAY924 Reg Expiry: 23 May 2020 WoF Expiry: **Odometer:** 26 Jul 2020 124,179 Kms **Good No:** 20328679 VIN: 7AT0H607X13296432 **Next Service:** 126,000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper poor fit R/H side/ Looks like its been in a light crash Bonnet poor fit and painted Black

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

26 Jun 2020 Inspected by: Murray Craig Date:

Name:

| | Pass | Fail | N/A | |
|--|--------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\sigma \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 5 | .0 | mm | |
| Right front | 5.0 | | mm | |
| Left rear | 7.0 | | mm | |
| Right rear | 7.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ' | | | |
| Dashboard warning lights | V | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | | | ~ | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| | | | | |

Signature: