

Report ID: 20,331,623 Version: 1 29 Jun 2020 Created:

Make:	Hyundai	Model:	Accent	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2002	Registration:	AKD146	Reg Expiry:	16 Oct 2020	Engine	1	I	I
WoF Expiry:		Odometer:	143,364 Kms	Good No:	20331623	Oil level		~	
VIN:	KMHCG51FR1U10042	Next Service:	143400	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S			W		Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210	E SC	Operation	~		
PT = paint def	ect NP				10111	Noise	~		
C = crack					R SC	Clutch	~		
P = pin dent	HIP				24116	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts D S						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
L/R Taillight Broken , Aerial mast Broken,						Tyres (lowest observed tread depth of tyres)			
					Left front 8.0			mm	
						Right front	6	.0	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Wet						Right rear	7	.0	mm
						Spare	re Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Oil seepage	e lower engine area & U	oper,				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	2	
Road Conditions During Test Drive: Wet						Central locking			~
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
	Deta: 20 lur 20	20							
Inspected by: Chris Buckley Date: 29 Jun 2020									

I have read and understood this condition guide.

Name:

Signature: