

Report ID: 20,335,692 Version: 2 06 Jul 2020 Created:

Signature: .....

Make:	Holden	Model:	Astra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2001		GNB10	Reg Expiry:	24 Aug 2020	Engine			1
WoF Expiry:		Odometer:	205,900 Kms	Good No:	20335692	Oil level	~		
VIN:	W0L0TGF4815262301			Service Histor		Smoke & fumes	~		+
					·	Performance	~		+
	port is not a warranty		for one could the	Doute have	haan diamandu l	Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		+
Key:	SC W	-0	PT PT		P SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ISC 6/6				PT SC	Operation	~		1
R = rust PT = paint def					JHIH	Noise	~		
C = crack				+	РТ	Clutch	-		~
P = pin dent						CV joints	~		-
* = decals	PT PIK			The	ENPR-	Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs W SC S SC D P						Performance	~		<u> </u>
				es may not be disp		Hand Brake	v v		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Broken rear parcel tray.Condisation inside rear screen.Head lights cloudy.Hood linning falling down						Tyres (lowest observed tread depth of tyres)   Left front 5 mm			
									mm
						Right front Left rear		5	mm
									mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						· ·	Spare Yes		
Engine has oil seepage.Front engine mount broken.Rust hole rear muffler. Chassis repair LH side inner wheel						Suspension			1
arch and ur		ie mount broken				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation		~	
	Average					Electrical / Accessories			1
Seats	5					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		──
Panels						Dashboard warning lights	~		—
Dashboa	ard Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u> Drives ok						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		<b> </b>
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	1	
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		<u> </u>
Engine Ti	ming Machanism	Comboli	-			Remote locking		~	<u> </u>
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 194,884						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: Y	es	Kms: 19	94,884	Reversing camera			~
Inspecte	d by: Mike Greenfield					Date: 06 Jul 202	0		
inspecte	a sy. Mine creemen						-		

I have read and understood this condition guide.

Name: .....