



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 20,337,890  |
| Version:   | 1           |
| Created:   | 06 Jul 2020 |

|                                    |        |             |                   |
|------------------------------------|--------|-------------|-------------------|
| Make:                              | Nissan | Body Style: | Hatchback         |
| Model:                             | Leaf   | VIN:        | 7AT0DH8KX20120818 |
| Year:                              | 2015   | Odometer:   | 68,586 Kms        |
| Road Conditions During Test Drive: | Dry    |             |                   |

| Electrical |                          | 30 | Fuel Flap Release      | ✓                              | Cooling System   |                  | 55  | Coolant Condition   | ✓                      | Exterior   |  | 78   | Under Carriage  | Good  |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
|------------|--------------------------|----|------------------------|--------------------------------|--|------------------|---|---|------------------------|--|--|--|---|---|--|--|---|--|--|---|---|--|---|---------------------------------|---------------------------------|---------------------------------|--|--|--|
| 1          | Battery                  | ✓  | 31                     | Reversing Camera               | ✓  | 56               | Performance   | ✓   | 79                     | Sun Roof Operation   |  | •  |   |   |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 2          | Headlights               | ✓  | 32                     | USB Port                       | •  | 57               | Radiator/Hoses (visual)   | ✓   | 80                     | Front Windscreen (no chips)  | Good   |  |   |   |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 3          | Tail Lights              | ✓  | 33                     | Window Lock Switch             | ✓  | Suspension       |   | 58  | Suspension Performance | ✓  | 81   | Back Windscreen (no chips)   | Good  |   |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 4          | High Stop Light          | ✓  | Transmission and Drive |                                | 34   | Operation        | ✓   | 59  | Steering Performance   | ✓  | 82   | Side Windows (no chips)  | Good  |   |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 5          | Front Right Indicators   | ✓  | 35                     | Noise                          | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> <td></td> <td></td> <td></td>  | 60               | Shock Absorbers   | ✓   | 83                     | Front Wiper Blades   | Good   |  |   |   |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 6          | Front Left Indicators    | ✓  | 36                     | Clutch                         | •  | Wheels and Tyres |   | 61  | Left Front             | 7  | mm   | 84   | Rear Wiper Blade  | Good  |  |  |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 7          | Rear Right Indicators    | ✓  | 37                     | CV Joints                      | ✓ <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>  | 62               | Right Front   | 7   | mm                     | 63   | Left Rear  | 7  | mm  | 85  | R/H Mirror   | Good   |   |  |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 8          | Rear Left Indicators     | ✓  | 38                     | Wheel Bearing                  | ✓ <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td>66</td> <td>Tools</td> <th>✓</th> <td>86</td> <td>L/H Mirror</td> <td>Good</td>   | 64               | Right Rear  | 7   | mm                     | 65   | Spare  | N/A  | 66  | Tools   | ✓  | 86   | L/H Mirror  | Good   |  |   |   |  |   |                                 |                                 |                                 |  |  |  |
| 9          | Reversing Lights         | ✓  | 39                     | Wheel Balance                  | ✓ <td>40</td> <td>Gearbox (Manual)</td> <td>•</td> <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th></th></th>   | 40               | Gearbox (Manual)  | •   | 67                     | AC Operation   | ✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th></th>  | 68   | Heater Fan  | ✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>87</td><td>L/F Guard</td><td>Good</td></th>   | 69   | Seatbelts  | ✓ <td>87</td> <td>L/F Guard</td> <td>Good</td>  | 87   | L/F Guard  | Good  |   |  |   |                                 |                                 |                                 |  |  |  |
| 10         | Rear Reflectors          | ✗  | 41                     | Engine Timing                  | Unknown  | 42               | Evidence of Cam Belt Replacement  | Not Applicable  | 70                     | Horn   | ✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>72</td> <td>Sun Visors</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>  | 71   | Seat Heaters  | •   | 72   | Sun Visors   | ✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>  | 88   | R/F Guard  | Good  |   |  |   |                                 |                                 |                                 |  |  |  |
| 11         | Hazard Lights            | ✓  | 43                     | Replaced at (odometer reading) |  | 43               | Replaced at (odometer reading)  |   | 73                     | Sun Visors Lights/Mirrors  | ✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>   | 74   | Seats   | Good  | 75   | Carpets  | Good  | 89   | L/H Doors  | Good  |   |  |   |                                 |                                 |                                 |  |  |  |
| 12         | Courtesy Lights          | ✓  | Brakes                 |                                | 44   | Front Brakes     | ✓ <td>45</td> <td>Rear Brakes</td> <th>✓<td>46</td><td>Handbrake</td><th>✓<td>47</td><td>Central Locking</td><th>✓<td>48</td><td>Remote Locking</td><th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th></th></th></th> | 45  | Rear Brakes            | ✓ <td>46</td> <td>Handbrake</td> <th>✓<td>47</td><td>Central Locking</td><th>✓<td>48</td><td>Remote Locking</td><th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th></th></th>               | 46   | Handbrake  | ✓ <td>47</td> <td>Central Locking</td> <th>✓<td>48</td><td>Remote Locking</td><th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th></th> | 47  | Central Locking  | ✓ <td>48</td> <td>Remote Locking</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>   | 48  | Remote Locking   | ✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>   | 90  | R/H Doors   | Good   |   |                                 |                                 |                                 |  |  |  |
| 13         | Dashboard Lights         | ✓  | Keys and Locking       |                                | 49   | Number of Keys   | 2   | 49  | Number of Keys         | 2  | 50   | Oil Level  | ✓ <td>51</td> <td>Smokes and Fumes</td> <td>•</td> <td>52</td> <td>Performance</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th> | 51  | Smokes and Fumes   | •  | 52  | Performance  | ✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>  | 91  | L/H Sill  | Good   |   |                                 |                                 |                                 |  |  |  |
| 14         | Dashboard Dimmer Switch  | ✓  | Engine                 |                                | 53   | Noise            | •   | 54  | Starter Motor          | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>56</td> <td>Performance</td> <th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th></th> | 55   | Smokes and Fumes   | •   | 56  | Performance  | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>   | 57  | Radiator/Hoses (visual)  | ✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>  | 92  | R/H Sill  | Good   |   |                                 |                                 |                                 |  |  |  |
| 15         | Number Plate Light       | ✓  | 50                     | Oil Level                      | ✓ <td>51</td> <td>Smokes and Fumes</td> <td>•</td> <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><td>•</td><td>54</td><td>Starter Motor</td><th>✓<td>55</td><td>Smokes and Fumes</td><td>•</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th></th>                              | 51               | Smokes and Fumes  | •   | 52                     | Performance  | ✓ <td>53</td> <td>Noise</td> <td>•</td> <td>54</td> <td>Starter Motor</td> <th>✓<td>55</td><td>Smokes and Fumes</td><td>•</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>                     | 53   | Noise   | •   | 54   | Starter Motor  | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>  | 55   | Smokes and Fumes   | •   | 93  | Boot/Tail Gate   | Good  |                                 |                                 |                                 |  |  |  |
| 16         | Dashboard Warning Lights | ✓  | 51                     | Smokes and Fumes               | •  | 52               | Performance   | ✓ <td>53</td> <td>Noise</td> <td>•</td> <td>54</td> <td>Starter Motor</td> <th>✓<td>55</td><td>Smokes and Fumes</td><td>•</td><td>56</td><td>Performance</td><th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th></th>                                   | 53                     | Noise  | •  | 54   | Starter Motor   | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>56</td> <td>Performance</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>           | 55   | Smokes and Fumes   | •   | 56   | Performance  | ✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>   | 94  | Front Bumper   | Good  |                                 |                                 |                                 |  |  |  |
| 17         | Speedo                   | ✓  | 52                     | Performance                    | ✓ <td>53</td> <td>Noise</td> <td>•</td> <td>54</td> <td>Starter Motor</td> <th>✓<td>55</td><td>Smokes and Fumes</td><td>•</td><td>56</td><td>Performance</td><th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th></th>                          | 53               | Noise   | •   | 54                     | Starter Motor  | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>56</td> <td>Performance</td> <th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>        | 55   | Smokes and Fumes  | •   | 56   | Performance  | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th> | 57   | Radiator/Hoses (visual)  | ✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>  | 95  | Rear Bumper  | Good  |                                 |                                 |                                 |  |  |  |
| 18         | Odometer                 | ✓  | 53                     | Noise                          | •  | 54               | Starter Motor   | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>56</td> <td>Performance</td> <th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th></th>                | 55                     | Smokes and Fumes   | •  | 56   | Performance   | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>96</td><td>Roof</td><td>Good</td></th></th>    | 57   | Radiator/Hoses (visual)  | ✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>96</td><td>Roof</td><td>Good</td></th>         | 58   | Suspension Performance   | ✓ <td>96</td> <td>Roof</td> <td>Good</td>   | 96  | Roof   | Good  |                                 |                                 |                                 |  |  |  |
| 19         | Rev Counter              | •  | 54                     | Starter Motor                  | ✓ <td>55</td> <td>Smokes and Fumes</td> <td>•</td> <td>56</td> <td>Performance</td> <th>✓<td>57</td><td>Radiator/Hoses (visual)</td><th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>59</td><td>Steering Performance</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td></th></th></th></th>       | 55               | Smokes and Fumes  | •   | 56                     | Performance  | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>59</td><td>Steering Performance</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td></th></th></th> | 57   | Radiator/Hoses (visual)   | ✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>59</td><td>Steering Performance</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td></th></th>     | 58   | Suspension Performance   | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td></th>         | 59   | Steering Performance   | ✓ <td>97</td> <td>Bonnet</td> <td>Good</td>   | 97  | Bonnet   | Good  |                                 |                                 |                                 |  |  |  |
| 20         | Fuel Gauge               | ✓  | 55                     | Smokes and Fumes               | •  | 56               | Performance   | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>59</td><td>Steering Performance</td><th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th></th></th>          | 57                     | Radiator/Hoses (visual)  | ✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>59</td><td>Steering Performance</td><th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th></th>          | 58   | Suspension Performance  | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th>             | 59   | Steering Performance   | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th>               | 60   | Shock Absorbers  | ✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>  | 98  | Fuel Cap   | ✓   |                                 |                                 |                                 |  |  |  |
| 21         | Wipers Front/Rear        | ✓  | 56                     | Performance                    | ✓ <td>57</td> <td>Radiator/Hoses (visual)</td> <th>✓<td>58</td><td>Suspension Performance</td><th>✓<td>59</td><td>Steering Performance</td><th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th></th> | 57               | Radiator/Hoses (visual)   | ✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>59</td><td>Steering Performance</td><th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th>           | 58                     | Suspension Performance   | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>99</td><td>Mud Flaps</td><th>✓</th></th></th>          | 59   | Steering Performance  | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>           | 60   | Shock Absorbers  | ✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>    | 61   | Left Front   | 7   | mm  | 99   | Mud Flaps   | ✓                               |                                 |                                 |  |  |  |
| 22         | Window Opener FL         | ✓  | 57                     | Radiator/Hoses (visual)        | ✓ <td>58</td> <td>Suspension Performance</td> <th>✓<td>59</td><td>Steering Performance</td><th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>100</td><td>WOF</td><th>✓</th></th></th></th>       | 58               | Suspension Performance  | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>100</td><td>WOF</td><th>✓</th></th></th>                | 59                     | Steering Performance   | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>100</td><td>WOF</td><th>✓</th></th>             | 60   | Shock Absorbers   | ✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>100</td> <td>WOF</td> <th>✓</th> | 61   | Left Front   | 7   | mm   | 62   | Right Front   | 7   | mm   | 100   | WOF                             | ✓                               |                                 |  |  |  |
| 23         | Window Opener FR         | ✓  | 58                     | Suspension Performance         | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>63</td><td>Left Rear</td><td>7</td><td>mm</td><td></td><td></td><td></td></th></th>                | 59               | Steering Performance  | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>63</td><td>Left Rear</td><td>7</td><td>mm</td><td></td><td></td><td></td></th>                       | 60                     | Shock Absorbers  | ✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td></td> <td></td> <td></td>   | 61   | Left Front  | 7   | mm   | 62   | Right Front   | 7  | mm   | 63  | Left Rear   | 7  | mm  |                                 |                                 |                                 |  |  |  |
| 24         | Window Opener RL         | ✓  | 59                     | Steering Performance           | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>7</td><td>mm</td><td>62</td><td>Right Front</td><td>7</td><td>mm</td><td>63</td><td>Left Rear</td><td>7</td><td>mm</td><td>64</td><td>Right Rear</td><td>7</td><td>mm</td><td></td><td></td><td></td></th>               | 60               | Shock Absorbers   | ✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td></td> <td></td> <td></td> | 61                     | Left Front   | 7  | mm   | 62  | Right Front   | 7  | mm   | 63  | Left Rear  | 7  | mm  | 64  | Right Rear   | 7   | mm                              |                                 |                                 |  |  |  |
| 25         | Window Opener RR         | ✓  | 60                     | Shock Absorbers                | ✓ <td>61</td> <td>Left Front</td> <td>7</td> <td>mm</td> <td>62</td> <td>Right Front</td> <td>7</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>7</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td></td> <td></td> <td></td>    | 61               | Left Front  | 7   | mm                     | 62   | Right Front  | 7  | mm  | 63  | Left Rear  | 7  | mm  | 64   | Right Rear   | 7   | mm  | 65   | Spare   | N/A                             |                                 |                                 |  |  |  |
| 26         | Rear View Mirrors        | ✓  | 61                     | Left Front                     | 7  | mm               | 62  | Right Front   | 7                      | mm   | 63   | Left Rear  | 7   | mm  | 64   | Right Rear   | 7   | mm   | 65   | Spare   | N/A   | 66   | Tools   | ✓ <td></td> <td></td> <td></td> |                                 |                                 |  |  |  |
| 27         | Radio (Basic Test Only)  | ✓  | 62                     | Right Front                    | 7  | mm               | 63  | Left Rear   | 7                      | mm   | 64   | Right Rear   | 7   | mm  | 65   | Spare  | N/A   | 66   | Tools  | ✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td></td><td></td><td></td></th></th> | 67  | AC Operation   | ✓ <td>68</td> <td>Heater Fan</td> <th>✓<td></td><td></td><td></td></th> | 68                              | Heater Fan                      | ✓ <td></td> <td></td> <td></td> |  |  |  |
| 28         | CD (Basic Test Only)     | ✓  | 63                     | Left Rear                      | 7  | mm               | 64  | Right Rear  | 7                      | mm   | 65   | Spare  | N/A   | 66  | Tools  | ✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td></td><td></td><td></td></th></th></th> | 67  | AC Operation   | ✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td></td><td></td><td></td></th></th> | 68  | Heater Fan  | ✓ <td>69</td> <td>Seatbelts</td> <th>✓<td></td><td></td><td></td></th> | 69  | Seatbelts                       | ✓ <td></td> <td></td> <td></td> |                                 |  |  |  |
| 29         | Boot Open Switch         | ✓  | 64                     | Right Rear                     | 7  | mm               | 65  | Spare   | N/A                    | 66   | Tools  | ✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td></td><td></td><td></td></th></th></th></th> | 67  | AC Operation  | ✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td>70</td><td>Horn</td><th>✓<td></td><td></td><td></td></th></th></th> | 68   | Heater Fan  | ✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td></td><td></td><td></td></th></th> | 69   | Seatbelts   | ✓ <td>70</td> <td>Horn</td> <th>✓<td></td><td></td><td></td></th> | 70   | Horn  | ✓ <td></td> <td></td> <td></td> |                                 |                                 |  |  |  |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

|  |                 |            |             |
|--|-----------------|------------|-------------|
| Inspected by:                                    | Mathew Varghese | Date:      | 06 Jul 2020 |
| I have read and understood this condition guide: |                 |            |             |
| Name:  |                 | Signature: |             |