

Report ID: 20,843,137 Version: 2 17 Jul 2020 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2014		HNH836	Reg Expiry:	29 Jul 2021	Engine			
WoF Expiry:		Odometer:	145,480 Kms	Good No:	20843137	Oil level	~		
VIN:	MR0EZ12G204158006	Next Service:		Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta harra nat		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	s sc	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc w			10		Operation	~		
R = rust PT = paint def				$\int$	JHIH	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent					세비	CV joints			~
* = decals	PSC 916			- NL	ETP D	Wheel bearings	~		•
SC = stone chips						Brakes	•		
W = significant scuffs W S SC						Performance	~		
		Note: som	e defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	() ()
Front screen chips.Front tyres inner edge wear.					Left front 4 mm				
						Right front			mm
						Left rear	2.		mm
Condition		a anti a mu				Right rear			mm
Conditions During Body Inspection:						Spare	2.6 mr Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
All okay	-					Suspension performance	~		
,						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	5		I
Road Conditions During Test Drive: Wet						Central locking	·		
Road Conditions During Test Drive: Wet						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
	-						<b>*</b>		
Inspected by: Mike Greenfield Date: 17 Jul 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....