

Report ID: 20,853,311 Version: 4 31 Jul 2020 Created:

Make:	Holden	Model:	Malibu	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	HCS827	<b>Reg Expiry:</b>	15 Jul 2021	Engine	•		
WoF Expiry:	14 Aug 2021	Odometer:	98,782 Kms	Good No:	20853311	Oil level	~		
VIN:	KL3GA69U9DB068914	Next Service:	112,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	lical inspection prior to	purchase and u	lis can be arranged ic	or an additional of	.narge.	Coolant condition	~		
	D SC W		S S P		S D	Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significant	D W	C		W	S D	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Stone chip on wind screen						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	.5	mm
						Right front	6.	.5	mm
						Left rear	6.	.5	mm
Conditions During Body Inspection: Wet						Right rear	6.	.5	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front wheel drive Left sill dent						Suspension performance	<		
Leit sill dell	l l					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	driver seat	worn				Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	<		
	iiu					Window winder FL	~		
						Window winder FR	<		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	<		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central los							<		
		<b></b>				Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Xinghui Lin Date: 31 Jul 2020									
Inspected by: Xinghui Lin Date: 31 Jul 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....