

Report ID: 20,855,169 Version: 1 23 Jul 2020 Created:

Make:	Toyota	Model:	Altezza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2001	Registration:	FYN416	Reg Expiry:	18 Sep 2020	Engine	I	I	I
WoF Expiry:	05 May 2021	Odometer:	239,990 Kms	Good No:	20855169	Oil level	~		
VIN:	7AT0H639X10079834	Next Service:	unknown	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	-	~	
Key:		-0	W SPT W	-161-		Radiator / Hoses (visual)		~	
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	v		
P = pin dent						CV joints	~		
* = decals PT SC PIP						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftyre	
Right cant rail dents and damage						Tyres (lowest observed tread depth of tyres)			mm
						Right front			-
						Left rear		.0	mm
									mm
Conditions During Body Inspection: Wet						Right rear	4.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Radiator cap broken Coolant leaks around water pump area						Suspension performance	~		
Engine oil leaks Minor diff oil leak						Steering performance		~	
Minor diff oil leak Wrong battery/terminals						Shock absorbers	~		
Power steering fluid leak around pump						Air Conditioning / Heater			
Interior Comments						Operation	~		
worp						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Poor					Indicators	~		
Panels	FOOI					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concerté						Window winder FR		~	
General Comments Drivers window not staying up						Window winder RL	~		
Drivers win	dow not staying up					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
		<u> </u>				Remote locking		~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Increast-		0							
Inspected by: Greg Morgan Date: 20 Jul 2020									
I have read and understood this condition guide. Name:									