

Report ID: 20,962,366 Version: 1 27 Jul 2020 Created:

Make:	Ford	Model:	Telstar GLI	Body Style:	Sedan		Pass	Fail	N/A
Year:	1993	Registration:	SC1390	Reg Expiry:	08 Dec 2020	Engine			
WoF Expiry:	03 Aug 2020	Odometer:	341,003 Kms	Good No:	20962366	Oil level	~		
VIN:		Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		c 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SDRSC	-0	SDRSC SDRP		S D R PT S	Radiator / Hoses (visual)	~		
S = scratch	Re	AU			X	Transmission	•		
D = dent	SDPTCS			The	S PT C SC	Operation	~		
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack					S R SC	Clutch			~
P = pin dent	Ho					CV joints		~	
* = decals	SDRSC 91			-NL	SDRSC	Wheel bearings	~	•	
SC = stone chips						Brakes			
W = significant scuffs SDR SC W SDR SC W SDR SC W SDR SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•		
Rear right indicator/taillight lens cracked at corner Left reversing light lens has moisture inside									mm
All mudflaps damaged						Right front			
Aerial not r	etracting					Left rear			mm mm
					Right rear	•		 mm	
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
Steering rad	-					Suspension performance	~		
	CV boots broken					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Stains					Head lights	~		
Jeats						Tail lights	~		
Carpets	Stains						~		╂───┦
Panels	Fabric loo	se, stains, parts m	nissing, scratches			Dashboard warning lights	~		┟───┤
Pariels						Wipers (front & rear)	~		┼──┤
Dashboa	rd Screw hole	es				Window winder FL	~		
	I					Window winder FR	~		├
<u>Gen</u> eral (	<u>Comments</u>					Window winder RL	~		╞──┤
						Window winder RR	~		├
						Rear view mirrors	~		╞──┤
						Radio (basic test only)	~		$\left  - \right $
						CD (basic test only)			~
						Number of keys	2		-
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Con	unions During Tes	t Drive:	Dry			Remote locking			~
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 275,159						Reversing camera			~
Inspected by: Matthew Dawson Date: 27 Jul 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....