

## **Basic Vehicle Condition Guide**

Report ID: 20,965,968


Version: 1

Created: 30 Jul 2020

Make: Model: Honda Accord **Body Style:** Sedan Year: 1995 Registration: ZN7186 Reg Expiry: 31 Aug 2020 WoF Expiry: **Odometer:** 20 Jan 2021 311,414 Kms **Good No:** 20965968 VIN: 7A88G130700101234 **Next Service:** 305,000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Right front park light lens scratched Dashboard controls not working

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Large engine oil leak

<u>Interior Comments</u>		
Seats	Poor	
Carpets	Average	
Panels	Average	
Dashboard	Good	

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

lan Dunn

**Evidence of Cam Belt Replacement:** Yes Kms: 250,000

Pass	Fail	N/A		
~				
~				
/				
~				
~				
~				
~				
~				
~				
		~		
~				
>				
~				
<b>&gt;</b>				
depth	of tyre	es)		
4.	.4	mm		
4.6		mm		
7.2		mm		
5.8		mm		
	Yes			
~				
>				
>				
Air Conditioning / Heater				
	~			
~				
>				
~				
~				
>				
	~			
~				
~				
~				
~				
<b>V</b>				
~				
<b>V</b>				
<b>V X</b> 3		·		
<b>V X</b> 3		<i>V</i>		
<b>V X</b> 3		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ		

I have read and understood this condition guide.

Name: .....

Signature: .....

29 Jul 2020

Date: