

Report ID: 20,981,146 Version: 1 06 Apr 2021 Created:

Make:	Toyota	Model:	Passo	Body Style: Hatchback][Pass	Fail	N/A
Year:	2007	Registration:	1 4550	Reg Expiry:	Engine		. un	
	01 Apr 2022	Odometer:	97,054 Kms	Good No: 20981146	Oil level	~		<u> </u>
VIN:	7AT0H650X20068525			Service History: No	Smoke & fumes	~		
	78101030820006323				Performance	~		
	port is not a warranty							
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Noise			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			<u> </u>
					Coolant condition	~		
Key:					Performance	~		
S = scratch	R	(0)	È		Radiator / Hoses (visual)	~		
D = dent					Transmission			
R = rust	MID	Operation	~					
PT = paint defe	ect				Noise	~		ļ
C = crack	14				Clutch			~
P = pin dent * = decals SC DDD					CV joints	~		
SC = stone chips					Wheel bearings	~		
W = significant scuffs					Brakes			
		N	P		Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishe	s may not be displayed in the diagram	Hand Brake	~		
LF seat belt trim missing					Tyres (lowest observed tread depth of tyres)			
					Left front	5.0)	mm
					Right front	5.0)	mm
					Left rear	5.0)	mm
Conditions During Body Inspection:					Right rear	5.0	5.0 mm	
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
Front whee	l drive				Suspension performance	~		
					Steering performance	~		
					Shock absorbers	~		
					Air Conditioning / Heater	I		L
					Operation	~		
Interior Comments					Electrical / Accessories			
Seats	Average				Head lights	~		
					Tail lights	~		<u> </u>
Carpets	Average				Indicators	~		
Panels	Average				Dashboard warning lights	~		
					Wipers (front & rear)	~		
Dashboa	rd Average				Window winder FL	~		
					Window winder FL	<i>v</i> <i>v</i>		
General Comments					Window winder RL			
						v		+
					Window winder RR	V		
					Rear view mirrors	~		
					Radio (basic test only)	~		
		CD (basic test only)		v				
					Number of keys	1		
Road Conditions During Test Drive: Dry					Central locking	~		<u> </u>
Enging Tir	ming Mechanism:	Timing (- Chain		Remote locking	~		
-	-	Sat. Nav. (basic test only)			~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			~
Inspected by: Mikhail Ri Date: 01 Apr 2021								

I have read and understood this condition guide.

Name:

Signature: