

Report ID: 20,990,765 Version: 4 15 Apr 2021 Created:

| Make: | Nissan | Model: | March | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------------------|----------------------|--|--------|------|-----|
| Year: | 2010 | Registration: | NJQ744 | Reg Expiry: | 14 Oct 2021 | Engine | | | L |
| WoF Expiry: | 09 Mar 2022 | Odometer: | 66,678 Kms | Good No: | 20990765 | Oil level | ~ | | |
| VIN: | 7AT0DH0KX20317618 | Next Service: | 76636 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | oration is made | for ago and milaago | Parts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | L |
| D = dent R = rust | HA | | | 715 | HIV | Operation | ~ | | |
| PT = paint defe | ect NP | | | $\left[\left(\right) \right]$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74114 | CV joints | ~ | | |
| * = decals | - Alt | | | The second | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significant | | | | | | Performance | ~ | | |
| Body Incr | position Commonts | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front 4.0 mr | | | mm |
| | | | | | | Right front | 4. | 0 | mm |
| | | | | | | Left rear | 7. | 0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 7.0 mm | | |
| Conditions Daming Dody inspection. Wet | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 11 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ird | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| 2WD. | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | - | | • | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Bobby Zhong Date: 20 Aug 2020 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: