



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	21,034,425
Version:	1
Created:	30 Sep 2020

Make:	Nissan	Body Style:	SUV
Model:	Elgrand	VIN:	7AT0DH6MX20012487
Year:	2011	Odometer:	132,699 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	8.8	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>8.7</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	8.7	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>8.6</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	8.6	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>8.5</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	8.5	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	✓ <td>65</td> <td>Spare</td> <td>No</td> <td>66</td> <td>Tools</td> <th>✓</th> <td>90</td> <td>R/H Doors</td> <td>Good</td>	65	Spare	No	66	Tools	✓	90	R/H Doors	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	68	Heater Fan	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td>	74	Seats	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td></th>	46	Handbrake	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td>	75	Carpets	Good	76	Panels	Good
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>78</td> <td>Under Carriage</td> <td>Good</td>	77	Dashboard	Good	78	Under Carriage	Good	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>79</td> <td>Fuel Cap</td> <th>✓</th> <td>80</td> <td>Front Windscreen (no chips)</td> <td>Good</td>	49	Number of Keys	2	79	Fuel Cap	✓	80	Front Windscreen (no chips)	Good
18	Odometer	✓	Engine		50	Oil Level	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td> <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td><td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	52	Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>85</td><td>R/H Mirror</td><td>Good</td><td>86</td><td>L/H Mirror</td><td>Good</td></th>	54	Starter Motor	✓ <td>85</td> <td>R/H Mirror</td> <td>Good</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	85	R/H Mirror	Good	86	L/H Mirror	Good
21	Wipers Front/Rear	✓	55	CD (Basic Test Only)	✓ <td>56</td> <td>Performance</td> <th>✓<td>87</td><td>L/F Guard</td><td>Good</td><td>88</td><td>R/F Guard</td><td>Good</td></th>	56	Performance	✓ <td>87</td> <td>L/F Guard</td> <td>Good</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	87	L/F Guard	Good	88	R/F Guard	Good
22	Window Opener FL	✓	57	Radio (Basic Test Only)	✓ <td>58</td> <td>Shock Absorbers</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td><td>90</td><td>R/H Doors</td><td>Good</td></th>	58	Shock Absorbers	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	89	L/H Doors	Good	90	R/H Doors	Good
23	Window Opener FR	✓	59	Starter Motor	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td><td>92</td><td>R/H Sill</td><td>Good</td></th>	59	Steering Performance	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	91	L/H Sill	Good	92	R/H Sill	Good
24	Window Opener RL	✓	60	Window Lock Switch	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	93	Boot/Tail Gate	Good	94	Front Bumper	Good
25	Window Opener RR	✓	61	Left Front	8.8	mm	61	Left Front	8.8	mm	95	Rear Bumper	Good	
26	Rear View Mirrors	✓	62	Right Front	8.7	mm	62	Right Front	8.7	mm	96	Roof	Good	
27	Radio (Basic Test Only)	✓	63	Left Rear	8.6	mm	63	Left Rear	8.6	mm	97	Bonnet	Good	
28	CD (Basic Test Only)	✓	64	Right Rear	8.5	mm	64	Right Rear	8.5	mm	98	Fuel Cap	✓	
29	Boot Open Switch	✓	65	Spare	No	65	Spare	No	66	Tools	✓ <td>99</td> <td>Mud Flaps</td> <td>✓</td>	99	Mud Flaps	✓
			66	Tools	✓ <td>66</td> <td>Tools</td> <th>✓<td>67</td><td>AC Operation</td><th>✓<td>100</td><td>WOF</td><td>✓</td></th></th>	66	Tools	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>100</td><td>WOF</td><td>✓</td></th>	67	AC Operation	✓ <td>100</td> <td>WOF</td> <td>✓</td>	100	WOF	✓
			67	AC Operation	✓ <td>67</td> <td>AC Operation</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td></td><td></td><td></td></th></th>	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td></td><td></td><td></td></th>	68	Heater Fan	✓ <td></td> <td></td> <td></td>			
			68	Heater Fan	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>69</td><td>Seatbelts</td><th>✓<td></td><td></td><td></td></th></th>	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td></td><td></td><td></td></th>	69	Seatbelts	✓ <td></td> <td></td> <td></td>			
			69	Seatbelts	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td></td><td></td><td></td></th></th>	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td></td><td></td><td></td></th>	70	Horn	✓ <td></td> <td></td> <td></td>			
			70	Horn	✓ <td>70</td> <td>Horn</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td></td><td></td><td></td></th>	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td></td> <td></td> <td></td>	71	Seat Heaters	•			
			71	Seat Heaters	•	71	Seat Heaters	•	72	Sun Visors	✓ <td></td> <td></td> <td></td>			
			72	Sun Visors	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>73</td><td>Sun Visors Lights/Mirrors</td><th>✓<td></td><td></td><td></td></th></th>	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td></td><td></td><td></td></th>	73	Sun Visors Lights/Mirrors	✓ <td></td> <td></td> <td></td>			
			73	Sun Visors Lights/Mirrors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td></td><td></td><td></td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td></td> <td></td> <td></td>	74	Seats	Good			
			74	Seats	Good	74	Seats	Good	75	Carpets	Good			
			75	Carpets	Good	75	Carpets	Good	76	Panels	Good			
			76	Panels	Good	76	Panels	Good	77	Dashboard	Good			
			77	Dashboard	Good	77	Dashboard	Good						

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ian Dunn	Date:	30 Sep 2020
---------------	----------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--